STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name Ryan Taylor

Address HC1 Box 71 Towner N. Dak

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 MILE

Well #3

Sec. (1 mile)

County McHenry

NW 1/4 SW 1/4 SW 1/4 Sec. 35 Twp. 155 N.Rg 75 W.

3. PROPOSED USE

☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for:

Chemcial Analysis? ☐ Yes ☐ No

Bacteriological Analysis? ☐ Yes ☐ No

If so, to what laboratory was it sent?

6. WELL CONSTRUCTION

Diameter of hole 8 inches. Depth 40 feet.

Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	4 inches	0 feet	40 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No

Perforated pipe set from 20 ft to 40 feet

Was casing left open end? ☐ Yes ☒ No

Was a well screened installed? ☐ Yes ☐ No

Material Diameter inches

Slot Size 25 set from 20 feet to 40 feet

Slot Size set from feet to feet

Was packer or seal used? ☐ Yes ☒ No

If so, what material Depth ft.

(stainless steel, bronze, etc.)

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From 0 To 20

Grouting Material: Cement Other

If other explain: Bentonite Pellets

Well head completion: Pitless unit

12" above grade yes Other

If other, specify

Was pump installed: ☐ Yes ☒ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 5 feet below surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump ☐ Bailer ☒ Other Air

Pumping level below land surface: estimated 50 GPM

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
fine silty Sands	0	15
Coarse sands		
some Lignite	15	42

(Use separate sheet if necessary)

10. DATE COMPLETED Oct 30, 1995

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☐ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Farmers Supply Co — 40

Driller's or Firm's Name — Certificate No.

Norwich N. Dak

Address

Harley B Thom — Oct 22, 1995

Signed by — Date

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY