STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Jim Sedler

Address: 8435 170 Av SE Hankinson, ND 58641

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 MILE

Brandenburg Township

County: Richland

Sec. (1 mile) ____

SE ¼ SE ¼ NE ¼ Sec. 5 Twp. 131 N. Rg 49 W.

3. PROPOSED USE

- [x] Domestic
- [x] Stock
- [ ] Geothermal
- [ ] Irrigation
- [ ] Municipal
- [ ] Monitoring
- [ ] Industrial
- [ ] Test Hole

4. METHOD DRILLED

- [ ] Cable
- [x] Forward Rotary
- [ ] Reverse Rotary
- [ ] Jetted
- [ ] Bored
- [ ] Auger

If other, specify ____

5. WATER QUALITY

Was a water sample collected for:

Chemcial Analysis? [ ] Yes [x] No

Bacteriological Analysis? [ ] Yes [x] No

If so, to what laboratory was it sent? ____

6. WELL CONSTRUCTION

Diameter of hole 6 7/8 inches. Depth 136 feet.

Casing: [ ] Steel [x] Plastic [ ] Concrete [ ] Threaded [ ] Welded [ ] Other

If other, specify ____

Pipe Weight:	Diameter:	From:	To:
____ lb/ft	4 inches	0 feet	132 feet
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet

Was perforated pipe used? [ ] Yes [x] No

Perforated pipe set from ____ ft to ____ feet

Was casing left open end? [ ] Yes [x] No

Was a well screened installed? [x] Yes [ ] No

Material SS Diameter 3 inches

Slot Size 12 set from 132 feet to 136 feet

Slot Size ____ set from ____ feet to ____ feet

Was packer or seal used? [x] Yes [ ] No

If so, what material Steel/rubber Depth 132 ft.

(stainless steel, bronze, etc.)

Type of well: Straight screen [ ] Gravel packed [x]

Depth grouted: From 0 To 40'

Grouting Material: Cement ____ Other Bentonite

If other explain: 3 50# bags bentonite mixed w/ 75 gals water

Well head completion: Pitless unit Mannor

12" above grade yes Other ____

If other, specify ____

Was pump installed: [x] Yes [ ] No

Was well disinfected upon completion? [x] Yes [ ] No

7. WATER LEVEL

Static water level ____ feet below surface

If flowing: closed-in pressure ____ psi

GPM flow ____ through ____ inch pipe

Controlled by: [ ] Valve [ ] Reducers [ ] Other

If other, specify ____

8. WELL TEST DATA

[ ] Pump [ ] Bailer [x] Other Air

Pumping level below land surface:

70 ft. after 1 hrs. pumping 50 gpm

____ ft. after ____ hrs. pumping ____ gpm

____ ft. after ____ hrs. pumping ____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Topsoil	0	2
Yellow clay	2	27
Soft gray clay	27	43
Soft Blue clay	43	107
cobbles	107	110
Medium blue clay (some rocks)	110	124
Coarse sand	124	125
Blue clay	125	128
Fine gray sand	128	132
Coarse gray sand	132	136
Medium gray sand	136	138

(Use separate sheet if necessary)

10. DATE COMPLETED 11/18/04

11. WAS WELL PLUGGED OR ABANDONED?

[x] Yes [ ] No

If so, how Bentonite

12. REMARKS:

Old well pump wore out, couldn't extract so drilled new. 55' from feed lot. Drilled by Nate Falk.

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Falk Bros. Well Drilling — Driller's or Firm's Name

79 — Certificate No

502 N Main Hankinson ND — Address

Signed by ____ Date 12-6-04

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY