STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name Clifford Erickson

Address Moffit N. D. 58560

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH



1 Mile

County Burleigh

SW ¼ SW ¼ SE ¼ Sec. 34 Twp. 137 N. Rg. 76 W.

3. PROPOSED USE

☐ Domestic ☐ Irrigation ☐ Industrial

☑ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☐ Reverse Rotary ☐ Bored

☑ Forward Rotary ☐ Jetted ☐ Other

If other, specify

5. WATER QUALITY

Was a water sample collected for chemical analysis?

☐ Yes ☑ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 7 7/8 inches. Depth 180 feet.

Casing: ☐ Steel ☑ Plastic ☐ Concrete

☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
SDR-40 lb/ft.	4 inches	0 feet	180 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☑ Yes ☐ No

Length of pipe perforated 30 feet

Was casing left open end? ☐ Yes ☑ No

Was a well screened installed? ☐ Yes ☑ No

Material _____ Diameter _____ inches
(stainless steel, bronze, etc.)

Slot size _____ set from _____ feet to _____ feet

Slot size _____ set from _____ feet to _____ feet

Slot size _____ set from _____ feet to _____ feet

Was a packer or seal used? ☐ Yes ☑ No

If so, what material

Type of well: Straight screen ☐ Gravel packed ☑

Was the well grouted? Yes ☑ No ☐

To what depth? 20 feet

Material used in grouting bentonite

Well head completion: Pitless adapter no

12" above grade yes Other

If other, specify

Was well disinfected upon completion? ☐ Yes ☐ No

7. WATER LEVEL

Static water level 30 feet below land surface

If flowing: closed-in pressure _____ psi

GPM flow _____ through _____ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump ☐ Bailer ☑ Other

Pumping level below land surface:

_____ ft. after _____ hrs. pumping _____ gpm

_____ ft. after _____ hrs. pumping _____ gpm

_____ ft. after _____ hrs. pumping _____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Topsoil	0	2
brown clay	2	37
coal	37	39
gray clay	39	48
blue shale clay	48	60
gray clay	60	72
brown waxy clay	72	148
blue gray sand	148	180

(Use separate sheet if necessary.)

10. DATE COMPLETED 11-15-82

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☑ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

H. E. McLean Drilling Co. 65

Driller's or Firm's Name Certificate No.

R. #5 Bismarck, N. D. 58501

Address

[illegible] 11-20-82

Signed by Date

DUPLICATE — BOARD'S COPY