STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Marvin Miller

Address: Brisbin N. Dak

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 Mile

Sec. [1 Mile]

County: Barnes

D ¼ D ¼ D ¼ Sec. 20 Twp. 141 N. Rg. 56 W.

3. PROPOSED USE

☐ Geothermal ☐ Monitoring
☑ Domestic ☐ Irrigation ☐ Industrial
☑ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☐ Reverse Rotary ☐ Bored
☑ Forward Rotary ☐ Jetted ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for chemical analysis?

☐ Yes ☑ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 10" inches. Depth 90' feet.

Casing: ☐ Steel ☐ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft.	5½ inches	feet	feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No

Perforated pipe set from 30' 35 ft to 40' 90 feet

Was casing left open end? ☒ Yes ☐ No

Was a well screened installed? ☐ Yes ☒ No

Material (stainless steel, bronze, etc.) Diameter inches

Slot size set from feet to feet

Slot size set from feet to feet

Was a packer or seal used? ☐ Yes ☒ No

If so, what material Depth Ft.

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From 0 To 20

Grouting Material: Cement X Other

If other explain:

Well head completion: Pitless unit NONE

12" above grade yes Other

If other, specify pasture well

Was pump installed: ☒ Yes ☐ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 26' feet below land surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump ☐ Bailer ☑ Other air

Pumping level below land surface:

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Black dirt	0	2
clay and yellow	2	35
Coarse sand	35	40
Blue clay	40	54
salen pellets fine sand	54	74
shale salen sand	74	85
Blue clay Rock	85	90

(Use separate sheet if necessary.)

10. DATE COMPLETED May 16, 1988

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☐ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Karen Water — No 17

Driller's or Firm's Name — Certificate No.

Valley City, N. Dak

Address

Box 356. Ahmed K. Karwi

Signed by — May 16, 1988 — Date

WHITE—DRILLER'S COPY YELLOW—BOARD'S COPY PINK—CUSTOMER'S COPY