STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name LeRoy Myren

Address Berlin, N. Dak

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH



1 Mile

County LaMoure

NE ¼ NE ¼ NE ¼ Sec. 9 Twp. 133 N. Rg. 62 W.

3. PROPOSED USE

☒ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED

☒ Cable ☐ Reverse Rotary ☐ Bored
☐ Forward Rotary ☐ Jetted ☐ Other

If other, specify

5. WATER QUALITY

Was a water sample collected for chemical analysis?

☐ Yes ☒ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 4 inches. Depth 155 feet.

Casing: ☒ Steel ☐ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
11 lb/ft.	4 inches	46 feet	151 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☐ Yes ☒ No

Length of pipe perforated feet

Was casing left open end? ☐ Yes ☒ No

Was a well screened installed? ☒ Yes ☐ No

Material Stainless steel Diameter 4 inches
(stainless steel, bronze, etc.) Watermark Super

Slot size 12 set from 150 feet to 155 feet

Slot size set from feet to feet

Slot size set from feet to feet

Slot size set from feet to feet

Was a packer or seal used? ☒ Yes ☐ No

If so, what material K-packer

Type of well: Straight screen ☒ Gravel packed ☐

Was the well grouted? Yes ☐ No ☐

To what depth? feet

Material used in grouting

Well head completion: Pitless adapter Monitor

12" above grade Other

If other, specify With thermometer submp

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 30 feet below land surface

If flowing: closed-in pressure psi

GPM flow 7 through 1¼ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☒ Pump ☐ Bailer ☐ Other

Pumping level below land surface:

30 ft. after 10 hrs. pumping 7 gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Black dirt	0	4
Yellow clay	4	17
Blue clay & fine sand	17	90
Blue clay, fine quick sand	90	120
fine sand	120	150
Coarse sand	150	155

(Use separate sheet if necessary.)

10. DATE COMPLETED May 24, 1978

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☒ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Beitz Pump Service Arthur J Beitz 113

Driller's or Firm's Name Certificate No.

Berlin, N Dak. 58415

Address

Signed by Date

DUPLICATE — BOARD'S COPY