STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Dean Heitkamp

Address: Wyndmere N.D.

2. WELL LOCATION

Sketch map location must agree with written location.



County: Richland county

____ ¼ ____ ¼ ____ ¼ Sec. 24 Twp. 133 N. Rg. 51 W.

3. PROPOSED USE

☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☐ Forward Rotary ☐ Reverse Rotary ☒ Jetted ☐ Bored ☐ Auger

If other, specify: _____

5. WATER QUALITY

Was a water sample collected for chemical analysis? ☒ Yes ☐ No

If so, to what laboratory was it sent: _____

6. WELL CONSTRUCTION

Diameter of hole 2 inches. Depth 49 feet.

Casing: ☒ Steel ☐ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify: _____

Pipe Weight:	Diameter:	From:	To:
3.65 lb/ft.	2 inches	51 feet	59 feet
~~3.65~~ lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☐ Yes ☒ No

Perforated pipe set from _____ ft to _____ feet

Was casing left open end? ☒ Yes ☐ No

Was a well screened installed? ☒ Yes ☐ No

Material: Plastic (stainless steel, bronze, etc.) Diameter 1¼ inches

Slot size .006 set from 39 feet to 47 feet

Slot size _____ set from _____ feet to _____ feet

Was a packer or seal used? ☒ Yes ☐ No

If so, what material: Brass Depth 39 Ft.

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From _____ To _____

Grouting Material: Cement _____ Other _____

If other explain: _____

Well head completion: Pitless unit no

12" above grade 16 in Other _____

If other, specify: _____

Was pump installed: ☐ Yes ☒ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 13.8 feet below land surface

If flowing: closed-in pressure _____ psi

GPM flow _____ through _____ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify: 1 – 2" Plunger

8. WELL TEST DATA

☒ Pump ☒ Bailer ☐ Other

Pumping level below land surface:

_____ ft. after 10 hrs. pumping 4¼ gpm

_____ ft. after _____ hrs. pumping _____ gpm

_____ ft. after _____ hrs. pumping _____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
clay	0	39
sand fine	39	47

(Use separate sheet if necessary.)

10. DATE COMPLETED Sep. 21 – 89

11. WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No

If so, how: _____

12. REMARKS: well made for Pasture for Livestock

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Frank's Well Service

Driller's or Firm's Name Certificate No.

Address: Mantador N.D.

Signed by Frank Fettes Date Oct 10-89

WHITE—DRILLER'S COPY YELLOW—BOARD'S COPY PINK—CUSTOMER'S COPY