STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name Clebert Johnson

Address Wyndmere

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 Mile

Sec. [1 Mile]

County 135 51

___ ¼ ___ ¼ NW ¼ Sec. 35 Twp. 131 N. Rg. 135 W.

3. PROPOSED USE

☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☒ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☐ Forward Rotary ☐ Reverse Rotary ☒ Jetted ☐ Bored ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for chemical analysis? ☒ Yes ☐ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 8 inches. Depth 59 feet.

Casing: ☒ Steel ☐ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
3.65 lb/ft.	8 inches	51 feet	59 feet
Pr. ft lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☐ Yes ☒ No

Perforated pipe set from ___ ft to ___ feet

Was casing left open end? ☐ Yes ☒ No

Was a well screened installed? ☒ Yes ☐ No

Material Plastic (stainless steel, bronze, etc.) Diameter 1¼ inches

Slot size 8 set from 51 feet to 59 feet

Slot size ___ set from 51 feet to 59 feet

Was a packer or seal used? ☒ Yes ☐ No

If so, what material Brass Depth 51 Ft.

Type of well: Straight screen ☒ Gravel packed ☐

Depth grouted: From ___ To ___

Grouting Material: Cement ___ Other ___

If other explain:

Well head completion: Pitless unit ___

12" above grade yes Other ___

If other, specify

Was pump installed: ☒ Yes ☐ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 13 feet below land surface

If flowing: closed-in pressure ___ psi

GPM flow ___ through ___ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☒ Pump ☐ Bailer ☐ Other

Pumping level below land surface:

___ ft. after 5 hrs. pumping 4 gpm

___ ft. after ___ hrs. pumping ___ gpm

___ ft. after ___ hrs. pumping ___ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
clay	0	13
fine sand	~~[illegible]~~	
	51 —	59

(Use separate sheet if necessary.)

10. DATE COMPLETED June 17-89

11. WAS WELL PLUGGED OR ABANDONED?

☒ Yes ☐ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Driller's or Firm's Name Frank's Well Service Certificate No.

Address Mantador N.D.

Signed by Frank Fettes Date

WHITE—DRILLER'S COPY YELLOW—BOARD'S COPY PINK—CUSTOMER'S COPY