STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Spencer Verry
Address: RR Bottineau

2. WELL LOCATION
Sketch map location must agree with written location.

NORTH

1 MILE

Sec. (1 mile)_____

County: Bottineau

NW 1/4 NE 1/4 SE 1/4 Sec. 10 Twp. 163 N. Rg. 75 W.

3. PROPOSED USE
☒ Domestic ☐ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify _____

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☒ Yes ☐ No
If so, to what laboratory was it sent? 1st Dist Health

6. WELL CONSTRUCTION
Diameter of hole 4 inches. Depth 219 feet.

Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify _____

Pipe Weight:	Diameter:	From:	To:
200 psi lb/ft	4 inches	0 feet	219 feet
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet

Was perforated pipe used? ☒ Yes ☐ No

Perforated pipe set from 199 ft. to 219 feet

Was casing left open end? ☒ Yes ☐ No

Was a well screen installed? ☒ Yes ☐ No

Material plastic Diameter 4 inches

Slot Size .020 set from 199 feet to 219 feet

Slot Size _____ set from _____ feet to _____ feet

Was packer or seal used? ☐ Yes ☒ No

If so, what material _____ Depth _____ ft.

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From 8 To 30

Grouting Material: Cement _____ Other No Clay

If other, explain: Bentonite Grout

Well head completion: Pitless unit Monitor

12" above grade yes Other _____

If other, specify _____

Was pump installed? ☒ Yes ☐ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 127 feet below surface

If flowing: closed-in pressure _____ psi

GPM flow _____ through ____ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify _____

8. WELL TEST DATA
☒ Pump ☐ Bailer ☐ Other

Pumping level below land surface:

161 ft. after 24 hrs. pumping 12 gpm

____ ft. after ____ hrs. pumping ____ gpm

____ ft. after ____ hrs. pumping ____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Top Soil	0	1
Yellow Clay	1	12
Gray Clay	12	30
Gravel spot.	30	31
Gray Clay	31	56
Rock	51	52
Blue Clay & Rock	52	196
med to coarse Gravel.	196	217
Blue Clay & Rock.	217	217

(Use separate sheet if necessary)

10. DATE COMPLETED Oct 8-01

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No

If so, how _____

12. REMARKS:
Well is for Cabin at Lake Metigoshe.

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

N-G Water Well Service 125
Driller's or Firm's Name — Certificate No.

1561 103rd St NE Bottineau
Address

Leslie D Nelson 10/30/01
Signed by — Date

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY