

WELL DRILLER'S REPORT

1. WELL OWNER

Name ARVID MUNSON

Address LAKOTA, N.D.

NORTH

1 Mile

County NE/Sou
NW 1/4 58 1/4 58 1/4 Sec. 33 Twp. 152 N. Rg. 60 W.

☐ Domestic ☐ Irrigation ☐ Industrial
☒ Stock ☐ Municipal ☐ Test Hole

☒ Cable
 ☐ Reverse Rotary
 ☐ Bored
☐ Forward Rotary
 ☐ Jetted
 ☐ Other
 If other, specify _____

Was a water sample collected for chemical analysis?
☐ Yes ☒ No
 If so, to what laboratory was it sent_____

Diameter of hole 8 inches. Depth 26 feet.

Casing: ☒ Steel ☐ Plastic ☐ Concrete
☒ Threaded ☐ Welded ☐ Other

If other, specify _____

Pipe Weight:	Diameter:	From:	To:
11 lb/ft.	4 inches	+2 feet	84 feet
_____ lb/ft.	_____ inches	_____ feet	_____ feet
_____ lb/ft.	_____ inches	_____ feet	_____ feet
_____ lb/ft.	_____ inches	_____ feet	_____ feet

Was perforated pipe used? ☐ Yes ☒ No
Length of pipe perforated _____ feet

Was casing left open end? ☒ Yes ☐ No

Was a well screened installed? ☐ Yes ☐ No

Material _____ Diameter _____ inches
(stainless steel, bronze, etc.)

Slot size_____ set from_____feet to_____feet

Slot size_____ set from_____feet to_____feet

Slot size_____ set from_____feet to_____feet

Slot size _____ set from _____ feet to _____ feet

Was a packer or seal used? ☐ Yes ☐ No

If so, what material _____

Type of well: Straight screen ☐ Gravel packed ☐

Was the well grouted? Yes ☒ No ☐

To what depth? 26 feet

Material used in grouting Cement

Well head completion: Pitless adapter_____

12" above grade ✓ Other _____

If other, specify _____

Was well disinfected upon completion? ☒ Yes ☐ No

Static water level 34 feet below land surface

If flowing: closed-in pressure_____psi

GPM flow _____ through _____ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify _____

☐ Pump ☒ Bailer ☐ Other

Pumping level below land surface:

58 ft. after 2 hrs. pumping 7-8 gpm

_____ft. after_____hrs. pumping_____gpm

_____ft. after_____hrs. pumping_____gpm

[illegible]

(Use separate sheet if necessary.)

10. DATE COMPLETED.

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☒ No

If so, how_____

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Driller's or Firm's Name RINGBOLT MILLING Certificate No. 49

McVie, N.D.

Address

Signed by Erwin Hansen Date 11-19-85