

WELL DRILLER'S REPORT

1. WELL OWNER

Name LUKE DION

Address LARROSA, N.D.

A 4x4 grid with the word "NORTH" written above it.

County Nelson 153
1/4 SE 1/4 Sec. 153 Twp. 60 N. Rg. 60 W.

☒ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole

☐ Cable ☐ Reverse Rotary ☐ Bored
☐ Forward Rotary ☐ Jetted ☐ Other

If so, to what laboratory was it sent _____

Casing: ☒ Steel ☐ Plastic ☐ Concrete
☒ Threaded ☐ Welded ☐ Other

Pipe Weight:	Diameter:	From:	To:
11 lb/ft.	4 inches	+1 feet	4 11 feet
lb/ft.	3 inches	63 feet	112 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Material _____ Diameter _____ inches
(stainless steel, bronze, etc.)

Slot size _____ set from _____ feet to _____ feet

If so, what material _____

Material used in grouting CEMENT

12" above grade ☒ Other ☐

If other, specify _____

Was well disinfected upon completion? ☒ Yes ☐ No

If other, specify _____

_____ ft. after	hrs. pumping	gpm
-----------------	--------------	-----

[illegible]

(Use separate sheet if necessary.)

If so, how _____

2. REMARKS: Rock at 19'
shale crumbly - put in liner -
used 3" Grundfos pump -
soft water, not salty.

HANSON Well DRILLING 110
Driller's or Firm's Name Certificate No.

McVine, N.D. 5825K

Signed by Donna Harris Date 11-18-99