STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Doug Striker

Address: Dunseith, N.D.

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH



1 Mile

County: Rolette

SE ¼ NE ¼ SW ¼ Sec. 9 Twp. 163 N. Rg. 72 W.

3. PROPOSED USE

☑ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☐ Reverse Rotary ☑ Bored
☐ Forward Rotary ☐ Jetted ☐ Other

If other, specify

5. WATER QUALITY

Was a water sample collected for chemical analysis?

☐ Yes ☑ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 24 inches. Depth 62 feet.

Casing: ☐ Steel ☐ Plastic ☑ Concrete
☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
265 lb/ft.	24 inches	+2 feet	62 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☑ Yes ☐ No

Length of pipe perforated 16 feet

Was casing left open end? ☐ Yes ☑ No

Was a well screened installed? ☐ Yes ☑ No

Material (stainless steel, bronze, etc.) Diameter inches

Slot size set from feet to feet

Slot size set from feet to feet

Slot size set from feet to feet

Slot size set from feet to feet

Was a packer or seal used? ☐ Yes ☑ No

If so, what material

Type of well: Straight screen ☐ Gravel packed ☑

Was the well grouted? Yes ☐ No ☑

To what depth? feet

Material used in grouting

Well head completion: Pitless adapter

12" above grade Other

If other, specify 24" above grade

Was well disinfected upon completion? ☐ Yes ☑ No

7. WATER LEVEL

Static water level 33 feet below land surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump ☑ Bailer ☐ Other

Pumping level below land surface:

42 ft. after 1 hrs. pumping 1½ gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Rocky Yellow Clay	0	7
Pebbly Yellow clay	7	41
Pebbly Blue Clay Sand streaks	41	49
Coarse Blue sand	49	51
Pebbly Blue Clay	51	62
Bed Solid		
16' P		
18' S		

(Use separate sheet if necessary.)

10. DATE COMPLETED 6-12-79

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☑ No

If so, how

12. REMARKS: rock at 8' Caving at 49 on down

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

CHURCH WELL BORING
BISBEE, N.D. 58317

Driller's or Firm's Name 126 Certificate No.

Address

Signed by Peter Church 6-12-79 Date

DUPLICATE — BOARD'S COPY