STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Kevin Bayko

Address: RR4 Minot ND Dak

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 Mile

Sec. [1 Mile]

County: WARD

OUTLOT 5 ¼ NW ¼ SE ¼ Sec. 19 Twp. 154 N. Rg. 81 W.

3. PROPOSED USE

☐ Geothermal ☐ Monitoring
☒ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED

☒ Cable ☐ Reverse Rotary ☐ Bored
☐ Forward Rotary ☐ Jetted ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for:

Chemical Analysis? ☐ Yes ☒ No

Bacteriological Analysis? ☒ Yes ☐ No

If so, to what laboratory was it sent: FIRST DIST HEALTH

6. WELL CONSTRUCTION

Diameter of hole: 4 inches. Depth: 68 feet.

Casing: ☒ Steel ☐ Plastic ☐ Concrete
☒ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
11 lb/ft.	4 inches	0 feet	67 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☐ Yes ☒ No

Perforated pipe set from ft to feet

Was casing left open end? ☐ Yes ☒ No

Was a well screened installed? ☒ Yes ☐ No

Material: STAINLESS STEEL (stainless steel, bronze, etc.) Diameter: 3 inches

Slot size: 25 set from 64 feet to 67 feet

Slot size: set from feet to feet

Was a packer or seal used? ☒ Yes ☐ No

If so, what material: Depth: Ft.

Type of well: Straight screen ☒ Gravel packed ☐

Depth grouted: From To

Grouting Material: Cement X Other

If other explain:

Well head completion: Pitless unit X

12" above grade Other

If other, specify

Was pump installed: ☐ Yes ☐ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level: 42 feet below land surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump ☐ Bailer ☒ Other

Pumping level below land surface:

64 ft. after 1 hrs. pumping 15 gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
TOP SOIL	0	5
SANDY CLAY	5	30
SAND	30	40
SAND & GRAVEL	40	47
GRAVEL & WATER	47	67
BLUE CLAY	67	

(Use separate sheet if necessary.)

10. DATE COMPLETED Sept 29, 1989

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☒ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

STEMEN DRILLING CO #7

Driller's or Firm's Name Certificate No.

340 1ST AVE

Address

BURLINGTON N DAK Nov 15, 1989

Signed by Delvin Stemen Date

WHITE—DRILLER'S COPY YELLOW—BOARD'S COPY PINK—CUSTOMER'S COPY