STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58501

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: David Davidson

Address: Tioga N. Dak.

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 Mile

Sec. [1 Mile]

County: Williams

¼ SW ¼ NE ¼ Sec. 16 Twp. 157 N. Rg. 95 W.

3. PROPOSED USE

☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☒ Cable ☐ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for:

Chemical Analysis? ☐ Yes ☒ No

Bacteriological Analysis? ☐ Yes ☐ No

If so, to what laboratory was it sent

6. WELL CONSTRUCTION

Diameter of hole 7 7/8 inches. Depth 125 feet.

Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft.	4 inches	0 feet	125 feet
lb/ft.	inches	feet	feet
lb/ft.	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No

Perforated pipe set from 122 ft to 125 feet

Was casing left open end? ☒ Yes ☐ No

Was a well screened installed? ☐ Yes ☐ No

Material Plastic Diameter 4 inches
(stainless steel, bronze, etc.)

Slot size 1/4 set from 122 feet to 125 feet

Slot size set from feet to feet

Was a packer or seal used? ☒ Yes ☐ No

If so, what material Mud Depth 110 Ft.

Type of well: Straight screen ☐ Gravel packed ☐

Depth grouted: From 0 To 20

Grouting Material: Cement ✓ Other

If other explain:

Well head completion: Pitless unit NO

12" above grade 24 Other

If other, specify

Was pump installed: ☒ Yes ☐ No

Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL

Static water level 100 feet below land surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☒ Pump ☐ Bailer ☐ Other

Pumping level below land surface:

120 ft. after 1 hrs. pumping 15 gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Top	0	1
Br. Til & Rock	1	82
Gray Clay	82	99
Fine Gray sandy Clay	99	122
Coal & Water	122	125

(Use separate sheet if necessary.)

10. DATE COMPLETED 8-27-91

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☒ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Tandeski water well Drill 21

Driller's or Firm's Name Certificate No.

RR 3 - Box 5 Tioga N. Dak -

Address

Dennis Tandeski 8-30-91

Signed by Date

WHITE—DRILLER'S COPY YELLOW—BOARD'S COPY PINK—CUSTOMER'S COPY