STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

334-1708

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name Chuck Hanson

Address

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 MILE

Sec. (1 mile)

County Divide

1/4 NE 1/4 SW 1/4 Sec. 19 Twp. 163 N. Rg 95 W.

3. PROPOSED USE

☐ Domestic ☑ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☑ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for: By owner

Chemical Analysis? ☐ Yes ☐ No

Bacteriological Analysis? ☐ Yes ☐ No

If so, to what laboratory was it sent?

6. WELL CONSTRUCTION

Diameter of hole 8 3/4 inches. Depth 37 feet.

Casing: ☐ Steel ☑ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	5 inches	1 feet	27 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☐ Yes ☑ No

Perforated pipe set from ft. to feet

Was casing left open end? ☐ Yes ☑ No

Was a well screen installed? ☑ Yes ☐ No

Material Plastic Diameter 5 inches

Slot Size .30 set from 27 feet to 37 feet

Slot Size set from feet to feet

Was packer or seal used? ☐ Yes ☐ No

If so, what material Depth ft.

Type of well: Straight screen ☐ Gravel packed ☑

Depth grouted: From 25 To 0-3

Grouting Material: Cement 0-3 Other Innuaplug

If other, explain:

Well head completion: Pitless unit

12" above grade Yes Other

If other, specify

Was pump installed? ☑ Yes ☐ No

Was well disinfected upon completion? ☐ Yes ☐ No

7. WATER LEVEL

Static water level 10 feet below surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☑ Pump ☐ Bailer ☐ Other

Pumping level below land surface:

33 ft. after 8 hrs. pumping 1 gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Loam	1	2
Clay	2	25
Sand	25	30
gravel	30	37

(Use separate sheet if necessary)

10. DATE COMPLETED 08-10-06

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☑ No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Rick Anlund 110

Driller's or Firm's Name Certificate No.

Crosby N.D.

Address

Rick Anlund 08-10-06

Signed by Date

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY