STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name Jordan Kreckla
Address Noonan

2. WELL LOCATION
Sketch map location must agree with written location.

NORTH

1 MILE

Sec. (1 mile) _____

County Burke

_____ 1/4 SW 1/4 SE 1/4 1/4 Sec. 32 Twp. 163 N. Rg 94 W.

3. PROPOSED USE
☐ Domestic ☐ Geothermal ☐ Monitoring
☑ Stock ☐ Irrigation ☐ Industrial
☐ Municipal ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☐ Reverse Rotary ☐ Bored
☑ Forward Rotary ☐ Jetted ☐ Auger

If other, specify _____

5. WATER QUALITY
Was a water sample collected for: By owner
Chemical Analysis? ☐ Yes ☐ No
Bacteriological Analysis? ☐ Yes ☐ No
If so, to what laboratory was it sent? _____

6. WELL CONSTRUCTION
Diameter of hole 8 3/4 inches. Depth 31 feet.

Casing: ☐ Steel ☑ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other

If other, specify _____

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	5 inches	0 feet	21 feet
_____ lb/ft	_____ inches	_____ feet	_____ feet
_____ lb/ft	_____ inches	_____ feet	_____ feet

Was perforated pipe used? ☐ Yes ☐ No
Perforated pipe set from _____ ft. to _____ feet
Was casing left open end? ☐ Yes ☑ No
Was a well screen installed? ☑ Yes ☐ No
Material Plastic Diameter 5 inches
Slot Size .20 set from 21 feet to 31 feet
Slot Size _____ set from _____ feet to _____ feet
Was packer or seal used? ☐ Yes ☑ No
If so, what material _____ Depth _____ ft.
Type of well: Straight screen ☐ Gravel packed ☑
Depth grouted: From 3 To 18
Grouting Material: Cement 3-Sacks Other Inverseplug
If other, explain: _____
Well head completion: Pitless unit _____
12" above grade Yes Other _____
If other, specify _____
Was pump installed? ☑ Yes ☐ No
Was well disinfected upon completion? ☑ Yes ☐ No

7. WATER LEVEL
Static water level 12 feet below surface
If flowing: closed-in pressure _____ psi
GPM flow _____ through _____ inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify _____

8. WELL TEST DATA
☑ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
12 ft. after 8 hrs. pumping 8 gpm
_____ ft. after _____ hrs. pumping _____ gpm
_____ ft. after _____ hrs. pumping _____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Loam	1	2
Clay	2	19
Coal	19	20
Sand	20	24
Gravel	24	31

(Use separate sheet if necessary)

10. DATE COMPLETED 7-29-06

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☑ No
If so, how _____

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Rick Rahmond — 110
Driller's or Firm's Name — Certificate No.

Crosby N.D.
Address

Rick Rahmond — 7-29-06
Signed by — Date

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY