STATE OF NORTH DAKOTA

BOARD OF WATER WELL CONTRACTORS

900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Rodger Friedt

Address: Hi Way #8 Mott N.D.

2. WELL LOCATION

Sketch map location must agree with written location.

NORTH

1 MILE

Sec. (1 mile) ____

County: Hettinger

SE 1/4 NW 1/4 SE 1/4 Sec. 1 Twp. 135 N. Rg 93 W.

3. PROPOSED USE

☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED

☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify ____

5. WATER QUALITY

Was a water sample collected for:

Chemical Analysis? ☐ Yes ☒ No

Bacteriological Analysis? ☐ Yes ☒ No

If so, to what laboratory was it sent? ____

6. WELL CONSTRUCTION

Diameter of hole 7 1/2 inches. Depth 117 feet.

Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify ____

Pipe Weight:	Diameter:	From:	To:
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet

Was perforated pipe used? ☒ Yes ☐ No

Perforated pipe set from 102 ft. to 117 feet

Was casing left open end? ☒ Yes ☐ No

Was a well screen installed? ☐ Yes ☒ No

Material ____ Diameter ____ inches

Slot Size ____ set from ____ feet to ____ feet

Slot Size ____ set from ____ feet to ____ feet

Was packer or seal used? ☐ Yes ☒ No

If so, what material ____ Depth ____ ft.

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From Top To 30'

Grouting Material: Cement Bentonite Other ____

If other, explain: ____

Well head completion: Pitless unit ____

12" above grade ✓ Other ____

If other, specify ____

Was pump installed? ☑ Yes ☐ No

Was well disinfected upon completion? ☐ Yes ☑ No

7. WATER LEVEL

Static water level 80 feet below surface

If flowing: closed-in pressure ____ psi

GPM flow ____ through ____ inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify ____

8. WELL TEST DATA

☐ Pump ☒ Bailer ☐ Other

Pumping level below land surface:

90' ft. after 1/2 hrs. pumping 10 gpm

____ ft. after ____ hrs. pumping ____ gpm

____ ft. after ____ hrs. pumping ____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Top Soil	0	1
Sandy Clay	1	20
yellow Sand	20	38
Clay	38	51
Coal	51	52
Clay	52	55
Sandy Clay	55	91
Gray Sand	91	146
Clay	146	117

(Use separate sheet if necessary)

10. DATE COMPLETED

Sept 20 - 08

11. WAS WELL PLUGGED OR ABANDONED?

☐ Yes ☒ No

If so, how ____

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Bezudoin Drilling 55

Driller's or Firm's Name — Certificate No.

921 14 Ave E Dickinson

Address

Wallace Berenberg

Signed by — Date

WHITE-DRILLER'S COPY YELLOW-BOARD'S COPY PINK-CUSTOMER'S COPY