

State of North Dakota
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD • BISMARCK, NORTH DAKOTA 58505

MONITORING WELL REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name Canadian Pacific Railway
Address 401 9 Ave SW - Ste 500
Calgary, AB T2P 4Z4, Canada

2. WELL LOCATION

Address (if in city) Lake St & Soo Line Rd
Lease 29761 Drake, ND 58736
County McHenry
SE 1/4 SE 1/4 SE 1/4 Sec. 3 Twp. 151 N. Rge. 76 W.
Lat.: 47° 55' 14.16" Long.: 100° 22' 15.73"
Altitude: 1645 ft

3. METHOD DRILLED

☒ Auger Other _____

4. WELL CONSTRUCTION

Diameter of Hole 10 inches Depth 20 feet
Riser: ☒ PVC ☐ Other
☒ Threaded ☐ Solvent ☐ Other
Riser rating SDR _____ Schedule 40
Diameter 2 inches
From 0 ft. to 10 ft.
Was a well screen installed? ☒ Yes ☐ No
Material PVC Diameter 2 inches
Slot Size 10 set from 10 feet to 20 feet
Sand packed from 9 to 20
Depth grouted from 0 to 9
Grouting Material
Bentonite Benseal Other _____
If other explain: _____

Well head completion:

24" above grade 6" Steel Pro-top Other _____
If other, specify _____
Was protective casing installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☐ Yes ☒ No

5. WATER LEVEL

Static water level _____ feet below surface
If flowing: closed-in pressure N/A psi or ft. above land surface

6. WELL LOG

Formation	Depth (Ft.)	
	From	To
Top Soil	8	2
Clay	2	15
Sandy Clay	15	20

(Use separate sheet if necessary)

7. WAS THE HOLE PLUGGED OR ABANDONED?

☐ Yes ☒ No
If so, how? _____

8. REMARKS

Monitoring Well

9. DATE COMPLETED 10/25/2012

10. CONTRACTOR CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

WCSC 432
Monitoring Well Contractor Certificate No.
14 Green River Rd, Morris, MN 56267
Address
[Signature] 11/12/12
Signature Date