STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name ADAM BRYANT
Address 4316 108TH ST NE.
ST JOHN ND 58369

2. WELL LOCATION
Sketch map location must agree with written location.

NORTH
1 MILE
Sec. (1 mile)

County ROLETTE
NE 1/4 NE 1/4 NE 1/4 Sec. 6 Twp. 163 N. Rg. 70 W.

3. PROPOSED USE
☐ Geothermal ☐ Monitoring
☒ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☐ Reverse Rotary ☐ Bored
☒ Forward Rotary ☐ Jetted ☐ Auger

If other, specify

5. WATER QUALITY
Was a water sample collected for: BY OWNER
Chemical Analysis? ☐ Yes ☐ No
Bacteriological Analysis? ☐ Yes ☐ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole 7 7/8 inches. Depth 232 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	5 inches	+2 feet	213 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No
Perforated pipe set from 213 ft. to 232 feet
Was casing left open end? ☐ Yes ☒ No
Was a well screen installed? ☒ Yes ☐ No
Material PVC Diameter 2 inches
Slot Size 15 set from 213 feet to 232 feet
Slot Size set from feet to feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material Depth ft.
Type of well: Straight screen ☐ Gravel packed ☒
Depth grouted: From 10 To 30
Grouting Material: Cement Other
If other, explain: BENTONITE CHIPS
Well head completion: Pitless unit YES
12" above grade YES Other
If other, specify
Was pump installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 44' feet below surface
If flowing: closed-in pressure psi
GPM flow through inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☒ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
65 ft. after 10 hrs. pumping 5 gpm
ft. after hrs. pumping gpm
ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
TOP SOIL	0	1
CLAY YELLOW	1	21
CLAY BLUE	21	34
CLAY YELLOW WITH SAND	34	44
CLAY BLUE SANDY	44	175
FINE BLUE SAND CLEAN	175	237

(Use separate sheet if necessary)

10. DATE COMPLETED 7-10-14

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

BURSINGER DRILLING 30
Driller's or Firm's Name Certificate No.
PO BOX 113 BISBEE ND 58317
Address
Charles Bursinger 10-28-14
Signed by Date

WELL OWNER'S COPY