STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE. DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Mike Uetsch
Address: 5991 28 Av NE
Rugby, N.D.

2. WELL LOCATION
Sketch map location must agree with written location.

GPS
EL

NORTH
1 MILE
Sec. (1 mile)

County: Pierce
NE 1/4 NW 1/4 ____ 1/4 Sec. 1 Twp. 153 N.Rg. 72 W.

3. PROPOSED USE
☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☐ Yes ☒ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole: 8 1/2 inches. Depth: 120 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
28 lb/ft	5 inches	+1 feet	120 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No
Perforated pipe set from 80 ft. to 120 feet
Was casing left open end? ☐ Yes ☒ No
Was a well screen installed? ☐ Yes ☒ No
Material ____ Diameter ____ inches
Slot Size ____ set from ____ feet to ____ feet
Slot Size ____ set from ____ feet to ____ feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material ____ Depth ____ ft.
Type of well: Straight screen ☐ Gravel packed ☒
Depth grouted: From 6 To 44
Grouting Material: Cement ____ Other X
If other, explain: Envirosplug
Well head completion: Pitless unit
12" above grade X Other
If other, specify
Was pump installed? ☐ Yes ☒ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 31 feet below surface
If flowing: closed-in pressure ____ psi
GPM flow ____ through ____ inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☐ Pump ☐ Bailer ☒ Other air
Pumping level below land surface:
70 ft. after 1 hrs. pumping 25+ gpm
____ ft. after ____ hrs. pumping ____ gpm
____ ft. after ____ hrs. pumping ____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Yellow sandy Clay	0	28
Brown gravel	28	36
Soft silty gray clay	36	38
gray sandy Clay gritty	38	75
Shaley gray Sandy Clay	75	88
Hard Clean Crumbly Sandy Shale	88	120

(Use separate sheet if necessary)

10. DATE COMPLETED 6-12-15

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Holbeck Water Well — 201
Driller's or Firm's Name — License No
8353 Hwy 2 Devilslake, N.D.
Address
Leo Johnson — 6-15-15
Signed by — Date

YELLOW BOARD'S COPY PINK-CUSTOMER'S COPY