STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED NOV - 5 2018 STATE WATER COMMISSION

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

18136989

1. WELL OWNER
Name: Brian Weis
Address: Wishek N. Dak

2. WELL LOCATION
Sketch map location must agree with written location.

NORTH
1 MILE
Sec. (1 mile)

County
1/4 1/4 1/4 Sec. 13 Twp. 131 N.Rg 72 W.

3. PROPOSED USE
☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☐ Yes ☒ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole 7 inches. Depth 140 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	4 inches	+1 feet	140 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☒ Yes ☐ No
Perforated pipe set from 100 ft. to 140 feet
Was casing left open end? ☒ Yes ☐ No
Was a well screen installed? ☐ Yes ☐ No
Material Diameter inches
Slot Size .020 set from 100 feet to 140 feet
Slot Size set from feet to feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material Depth ft.
Type of well: Straight screen ☐ Gravel packed ☒
Depth grouted: From 10 To 50
Grouting Material: Cement Other Enviroplug
If other, explain:
Well head completion: Pitless unit yes
12" above grade yes Other
If other, specify
Was pump installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 54 feet below surface
If flowing: closed-in pressure psi
GPM flow through inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☒ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
62 ft. after 5 hrs. pumping 18 gpm
ft. after hrs. pumping gpm
ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Till	0	2
Brown Sandy Clay	2	57
Gray Clay	57	70
Blue Gray Sand	70	135
Gray Clay	135	140

(Use separate sheet if necessary)

10. DATE COMPLETED 10-18-18

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.
Bob's Drilling & Excavating — Driller's or Firm's Name
64 — Certificate No.
Zeeland N. Dak — Address
Robert Schumacher — Signed by
10-21-18 — Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY