STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED
AUG - 2 2021
ND DEPT. OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Mitch Homan
Address: Fargo

2. WELL LOCATION
Sketch map location must agree with written location.

GPS
EL

NORTH
1 MILE
Sec. (1 mile)

County: Emmons
SE 1/4 SW 1/4 NW 1/4 Sec. 31 Twp. 135 N. Rg. 78 W.

3. PROPOSED USE
☐ Domestic ☑ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☑ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☑ No
Bacteriological Analysis? ☐ Yes ☑ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole 7 7/8 inches. Depth 229 feet.
5" 229 – 400
Casing: ☐ Steel ☑ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
SDR 21 lb/ft	5 inches	0 feet	229 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☐ Yes ☐ No
Perforated pipe set from ft. to feet
Was casing left open end? ☑ Yes ☐ No
Was a well screen installed? ☐ Yes ☑ No
Material Diameter inches
Slot Size set from feet to feet
Slot Size set from feet to feet
Was packer or seal used? ☐ Yes ☐ No
If so, what material Depth ft.
Type of well: Straight screen ☐ Gravel packed ☐
Depth grouted: From 0 – 150 To 30 – 190
Grouting Material: Cement Other Bentonite
If other, explain:
Well head completion: Pitless unit
12" above grade Other
If other, specify
Was pump installed? ☑ Yes ☐ No
Was well disinfected upon completion? ☑ Yes ☐ No

7. WATER LEVEL
Static water level 185 feet below surface
If flowing: closed-in pressure psi
GPM flow through inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☐ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
195 ft. after 5 hrs. pumping 9 gpm
ft. after hrs. pumping gpm
ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Brown sandy clay	0	35
Gray clay	35	130
Gray sand	130	180
Fine muddy sand	180	220
Gray clay w/sand streaks & shale chips	220	400

(Use separate sheet if necessary)

10. DATE COMPLETED 6-7-21

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☑ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Quick Silver Well — 21
Driller's or Firm's Name — Certificate No.

Driscoll
Address

Aaron Berg — 7-15-21
Signed by — Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY