

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

[illegible]

Pitless Unit and Pump Record

Well Owner:

Name John Buskohl

Date of Installation: 11/1/22

Address 740 5th Ave, Milwau, N.D. 58060

Location:

County SARGENT

SW 1/4, SE 1/4, SE 1/4 Section 1, Township 131, N., Range 55 West

Well Head Completion:

Pitless Unit brand name Monlor, diameter 6x5 in., type of joint Mech

depth of joint 4 inches above grade 12, other _____

Pump:

Type: submersible ☒, jet _____, cylinder _____, turbine _____, other _____

Manufacturer's name Flowise

Model No. 10921 HP 3/4 Volts 240

Pump setting (depth), 120, pumping rate 10 gpm.

Is well vented? yes ☒ no _____ Is there a measuring port? yes ☒ no _____

Pressure tank (if installed) Yes ☒ No _____

Manufacturer's name Well-x-trol Model No. 203 Capacity 32 gallons

above ground ☒ below ground _____

Pressure rating of pipe between well and tank 200

Was well and other plumbing disinfected upon completion? Yes ☒ No _____

Installer's Certification

This installation was installed under my jurisdiction and this report is true to the best of my knowledge.

Wieber Well Drilling
INSTALLER OR FIRM NAME

Box 157, Lidgerwood, N.D. 58053
ADDRESS

Jung Wieber
SIGNED BY

190
CERTIFICATE NO.

11/1/22
DATE