



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

NOV 22 2022

RECEIVED

NOV 22 2022

ND DEPT. OF WATER RESOURCES

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name <u>Wesley Berg</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>1240 Hwy 31 - Stanton ND 58571</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>30'</u>			
		County <u>Oliver</u>		GPS <u>X</u>		If Flowing, Closed-In Pressure In PSI	
		1/4 <u>47.26293° N</u>	1/4	1/4	GPM Flow Through Inch Pipe		
		Township <u>101.35760° W</u>	Range	Section	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify		
PROPOSED USE <u>14308408 CDC</u>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify				Feet After <u>70</u> Hrs. Pumping <u>10</u> GPM <u>20</u>			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <u>9 7/8</u>		Depth In Feet <u>80</u>		<u>Top soil</u> <u>0</u> <u>2</u>			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify				<u>Brown clay</u> <u>2</u> <u>16</u>			
Pipe Weight lb/ft <u>2.9</u>	Diameter inches <u>5</u>	From feet <u>+3</u>	To feet <u>40</u>	<u>Sandy grey clay</u> <u>16</u> <u>36</u>			
				<u>grey sand</u> <u>36</u> <u>42</u>			
				<u>Sandy grey clay</u> <u>42</u> <u>46</u>			
				<u>grey sand w/ coal streaks</u> <u>46</u> <u>74</u>			
				<u>grey sand + gravel</u> <u>74</u> <u>84</u>			
				<u>grey clay + gravel</u> <u>84</u> <u>90</u>			
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☐ Yes ☒ No				DATE COMPLETED <u>10-30-22</u>			
Screen Or Perforation Interval From In Feet To In Feet				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Was Casing Left Open End? ☐ Yes ☒ No				If So, How			
Material <u>PVC</u>		Diameter In Inches <u>5</u>		REMARKS			
Slot Size <u>0.016</u>	Set From In Feet <u>40</u>	To In Feet <u>80</u>		<u>Owner got water tested</u>			
Slot Size	Set From In Feet	To In Feet		DRILLER'S CERTIFICATION			
Was Packer Or Seal Used? ☐ Yes ☒ No				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
If So, What Material		Depth In Feet		Driller's Or Firm's Name <u>Depth Well Drilling</u> Certificate Number <u>188</u>			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				Address <u>PO Box 3100 - Minot ND 58702</u>			
Depth Grouted From <u>0</u> To <u>35'</u>				Signed By <u>Dan L</u> Date <u>11-4-22</u>			
Grouting Material Cement Other <u>X</u>							
If Other, Explain: <u>3/8" Bentonite chips</u>							
Well Head Completion: Pitless Unit <u>No</u>							
12" Above Grade		Other (Specify) <u>+36"</u>					
If Other, Specify							