



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

NOV 29 2022

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name <u>Kevin Hansen</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>18000 22nd St SW - Ryder ND 58719</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>35'</u>			
		County <u>Ward</u>		GPS <u>X</u>		If Flowing, Closed-In Pressure In PSI	
		1/4 <u>48.04991° N</u>	1/4	1/4	GPM Flow Through Inch Pipe		
		Township <u>101-64384° W</u>	Range	Section	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify		
PROPOSED USE <u>1530BS30AAD</u>				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial				☒ Pump ☐ Bailer ☐ Other			
☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				Pumping Level Below Land Surface			
METHOD DRILLED				Feet After <u>70</u> Hrs. Pumping <u>14</u> GPM <u>10</u>			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary				Feet After Hrs. Pumping GPM			
☐ Bored ☐ Auger ☐ If Other, Specify				Feet After Hrs. Pumping GPM			
WATER QUALITY Was a water sample collected for				WELL LOG			
Chemical Analysis? ☐ Yes ☒ No				Formation Depth (ft.)			
Bacteriological Analysis? ☐ Yes ☒ No				From To			
If So, To What Laboratory Was It Sent?				<u>Sandy Top Soil</u> <u>0</u> <u>1</u>			
WELL CONSTRUCTION				<u>Course sand & gravel</u> <u>1</u> <u>20</u>			
Diameter Of Hole In Inches <u>9 7/8</u>		Depth In Feet <u>77</u>		<u>Gravel</u> <u>20</u> <u>27</u>			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other				<u>Coal</u> <u>27</u> <u>28</u>			
☐ Threaded ☐ Welded ☐ If Other, Specify				<u>grey clay</u> <u>28</u> <u>42</u>			
Pipe Weight <u>2.9</u> lb/ft	Diameter <u>5</u> inches	From <u>+3</u> feet	To <u>37</u> feet	<u>gravel w/ little clay</u> <u>42</u> <u>62</u>			
<u>2.9</u> lb/ft	<u>5</u> inches	<u>+3</u> feet	<u>37</u> feet	<u>grey sand & gravel</u> <u>62</u> <u>68</u>			
<u>2.9</u> lb/ft	<u>5</u> inches	<u>+3</u> feet	<u>37</u> feet	<u>Coal</u> <u>68</u> <u>69</u>			
<u>2.9</u> lb/ft	<u>5</u> inches	<u>+3</u> feet	<u>37</u> feet	<u>gravel w/ a little clay</u> <u>69</u> <u>82</u>			
<u>2.9</u> lb/ft	<u>5</u> inches	<u>+3</u> feet	<u>37</u> feet	<u>grey clay w/ gravel</u> <u>82</u> <u>102</u>			
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☐ Yes ☒ No				DATE COMPLETED <u>11-5-22</u>			
Screen Or Perforation Interval		From In Feet	To In Feet	WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
Was Casing Left Open End? ☐ Yes ☒ No				If So, How			
Material <u>PVC</u>		Diameter In Inches <u>5</u>		REMARKS			
Slot Size <u>0.016</u>	Set From In Feet <u>37</u>	To In Feet <u>77</u>		<u>Owner to get water tested</u>			
Slot Size	Set From In Feet	To In Feet		DRILLER'S CERTIFICATION			
Was Packer Or Seal Used? ☐ Yes ☒ No				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
If So, What Material		Depth In Feet		Driller's Or Firm's Name <u>Dan Well Drilling</u> Certificate Number <u>198</u>			
Type Of Well ☐ Straight Screen ☒ Gravel Packed		Depth Grouted <u>0</u> From <u>0</u> To <u>35'</u>		Address <u>PO Box 3100 - Minot ND 58702</u>			
Grouting Material <u>Cement</u>		Other (Specify) <u>+36"</u>		Signed By <u>Dan</u> Date <u>11-14-22</u>			
If Other, Explain: <u>3/8 Bentonite chips</u>							
Well Head Completion: Pitless Unit <u>No</u>							
12" Above Grade		Other (Specify)					
It Other, Specify							