



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

NOV 24 2023

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No <i>Solar - future</i>			
Name <i>US Forest Service</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>1601 Main St. Lisbon ND 58054</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>8</i>			
		County <i>Richland</i>		GPS		If Flowing, Closed-In Pressure In PSI	
		1/4 <i>NW</i>		1/4 <i>SE</i>		GPM Flow Through Inch Pipe	
		Township <i>134N</i>		Range <i>52W</i>		Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify	
		Section <i>8</i>					
PROPOSED USE <i>13405208BDB</i>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial				☒ Pump ☐ Bailer ☐ Other			
☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				Pumping Level Below Land Surface			
METHOD DRILLED				Feet After <i>5</i> Hrs. Pumping <i>2</i> GPM <i>30</i>			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary				Feet After Hrs. Pumping GPM			
☐ Bored ☐ Auger ☐ If Other, Specify				Feet After Hrs. Pumping GPM			
WATER QUALITY Was a water sample collected for				WELL LOG			
Chemical Analysis? ☐ Yes ☒ No				Formation Depth (ft.)			
Bacteriological Analysis? ☐ Yes ☒ No				From To			
If So, To What Laboratory Was It Sent?				<i>Brown sand</i> <i>0</i> <i>12</i>			
WELL CONSTRUCTION				<i>Silty sand</i> <i>12</i> <i>14</i>			
Diameter Of Hole In Inches <i>1 1/2</i>		Depth In Feet <i>33</i>		<i>Water sand</i> <i>14</i> <i>33</i>			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other							
☐ Threaded ☐ Welded ☐ If Other, Specify							
Pipe Weight	Diameter	From	To				
<i>220</i> lb/ft	inches	<i>23</i> feet	<i>+ 2</i> feet				
lb/ft	inches	feet	feet				
lb/ft	inches	feet	feet				
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval	From In Feet	To In Feet					
	<i>33</i>	<i>23</i>					
Was Casing Left Open End? ☐ Yes ☒ No							
Material <i>PVC</i>		Diameter In Inches <i>4</i>		Use Separate Sheet If Necessary			
Slot Size <i>15</i>	Set From In Feet <i>33</i>	To In Feet <i>23</i>		DATE COMPLETED <i>10/22/23</i>			
Slot Size	Set From In Feet	To In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Was Packer Or Seal Used? ☐ Yes ☒ No				If So, How			
If So, What Material		Depth In Feet		REMARKS			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				<i>purpose good</i>			
Depth Grouted	From	To		DRILLER'S CERTIFICATION			
	<i>23</i>	<i>3</i>		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Grouting Material	Cement	<i>Bentonite</i>		Driller's Or Firm's Name <i>Sh. Swandal / Andy Noheby</i> Certificate Number <i>#109</i>			
If Other, Explain:				Address <i>Walcott ND</i>			
Well Head Completion: Pitless Unit <i>well seal</i>				Signed By <i>Sh. Swandal</i> Date <i>11/20/23</i>			
12" Above Grade		Other (Specify)					
It Other, Specify							