STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED
FEB 02 2024
ND DEPT. OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Piper Land Management
Address: Moorehead Mnn.

2. WELL LOCATION
Sketch map location must agree with written location.

GPS 46° 8' 24" N
103° 31' 26" W

EL 3040
13110326DBB

NORTH
1 MILE
Sec. (1 mile)

County: Bowman
____ 1/4 ____ 1/4 ____ 1/4 Sec. ____ Twp. ____ N. Rg ____ W.

3. PROPOSED USE
☐ Domestic ☒ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☒ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☐ Yes ☒ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole 8.75 inches. Depth 255 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
200 lb/ft	5 inches	-7 feet	235 feet
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet

Was perforated pipe used? ☐ Yes ☒ No
Perforated pipe set from ____ ft. to ____ feet
Was casing left open end? ☐ Yes ☒ No
Was a well screen installed? ☒ Yes ☐ No
Material PVC Diameter 5 inches
Slot Size .016 set from 235 feet to 255 feet
Slot Size ____ set from ____ feet to ____ feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material ____ Depth ____ ft.
Type of well: Straight screen ☐ ~~Gravel~~ Silica packed ☒
Depth grouted: From -7 To 230
Grouting Material: Cement ____ Other Bentonite
If other, explain:
Well head completion: Pitless unit Yes
12" above grade X Other
If other, specify
Was pump installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 68 feet below surface
If flowing: closed-in pressure ____ psi
GPM flow ____ through ____ inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☒ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
115 ft. after 2 hrs. pumping 10 gpm
____ ft. after ____ hrs. pumping ____ gpm
____ ft. after ____ hrs. pumping ____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Clay brown	0	18
Clay brown/sandy	18	91
rock	91	92
clay grey/sandy/thin rock seams	92	117
Clay black/sandy	117	155
coal	155	158
Clay dark grey	158	200
Powder w/ clay seams	200	232
coal	232	255
Clay dark grey	255	

(Use separate sheet if necessary)

10. DATE COMPLETED 11-15-23

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Milo Burwick & Sons LLC — Driller's or Firm's Name
91 — Certificate No.
Dickinson ND — Address
Dale M Burwick — Signed by
11-21-23 — Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY