

FEB 02 2024

ND DEPT. OF WATER RESOURCES

1. WELL OWNER

NameJustin Bouisma

AddressGladstone ND

2. WELL LOCATION

Sketch map location must agree with written location.

GPS

EL13509526AA

CountyHettinger

1/4 NE 1/4 NE 1/4 Sec. 26 Twp. 135 N. Rg. 95 W.

3. PROPOSED USE

☐ Domestic

☒ Stock

☐ Geothermal

☐ Irrigation

☐ Municipal

☐ Monitoring

☐ Industrial

☐ Test Hole

4. METHOD DRILLED

☐ Cable

☒ Forward Rotary

☐ Reverse Rotary

☐ Jetted

☐ Bored

☐ Auger

If other, specify

5. WATER QUALITY

Was a water sample collected for:

Chemical Analysis?

Bacteriological Analysis?

Yes

Yes

No

No

If so, to what laboratory was it sent?

6. WELL CONSTRUCTION

Diameter of hole8.75 inches. Depth23 feet.

Casing:

☐ Steel

☒ Plastic

☐ Concrete

☐ Threaded

☐ Welded

☐ Other

If other, specify

Pipe Weight:

Diameter:

From:

To:

200 lb/ft

5 inches

7 feet

53 feet

lb/ft

inches

feet

feet

lb/ft

inches

feet

feet

Was perforated pipe used?

Yes

No

Perforated pipe set from feet. to feet

Was casing left open end?

Yes

No

Was a well screen installed?

Yes

No

MaterialPVC Diameter5 inches

Slot Size020 set from53 feet to23 feet

Slot Size set from feet to feet

Was packer or seal used?

Yes

No

If so, what material Depth ft.

Type of well: Straight screen ☐ Gravel packed ☒

Depth grouted: From7 To42

Grouting Material: Cement OtherBentonite

If other, explain:

Well head completion: Pitless unit Yes

12" above grade Other18"

If other, specify

Was pump installed?

Yes

No

Was well disinfected upon completion?

Yes

No

7. WATER LEVEL

Static water level12 feet below surface

If flowing: closed-in pressure psi

GPM flow through inch pipe

Controlled by: ☐ Valve ☐ Reducers ☐ Other

If other, specify

8. WELL TEST DATA

☐ Pump

☐ Bailer

☒ Air

Other

Pumping level below land surface:

30 ft. after2 hrs. pumping30 gpm

ft. after hrs. pumping gpm

ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.)	
	From	To
sand brown med	0	5
gravel, sand mix	5	8
sand blue fine	8	41
rock	41	42
sandstone	42	44
sand blue fine	44	65.5
rock	65.5	67
sand blue fine	67	73
clay grey soft	73	

(Use separate sheet if necessary)

10. DATE COMPLETED10-22-23

11. WAS WELL PLUGGED OR ABANDONED?

Yes

No

If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Milo Beerwick Sons LLC 91

Driller's or Firm's Name Certificate No.

Dickinson ND

Address

Signed by

Date10-24-23