STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED
FEB 21 2024
ND DEPT. OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Jerrie Hauser
Address: Glen Ullin ND

2. WELL LOCATION
Sketch map location must agree with written location.

GPS
EL 14008832DCD

NORTH
1 MILE
Sec. (1 mile)

County: Morton
1/4 1/4 SE 1/4 Sec. 32 Twp. 140 N. Rg. 88 W.

3. PROPOSED USE
☐ Domestic ☐ Geothermal ☐ Monitoring
☐ Stock ☐ Irrigation ☐ Industrial
☐ Municipal ☐ Test Hole

4. METHOD DRILLED
☐ Cable ☐ Reverse Rotary ☐ Bored
☒ Forward Rotary ☐ Jetted ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☐ Yes ☒ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole 7 7/8 inches. Depth 60 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
SDR 21 lb/ft	4 inches	0 feet	60 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☐ Yes ☐ No
Perforated pipe set from 50 ft. to 60 feet
Was casing left open end? ☐ Yes ☒ No
Was a well screen installed? ☒ Yes ☐ No
Material PVC Diameter 4 inches
Slot Size 16 set from 50 feet to 60 feet
Slot Size set from feet to feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material Depth ft.
Type of well: Straight screen ☐ Gravel packed ☒
Depth grouted: From 45-40 to 30-8
Grouting Material: Cement Other
If other, explain: BENT CHIPS
Well head completion: Pitless unit YES
12" above grade YES Other
If other, specify
Was pump installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level 17 feet below surface
If flowing: closed-in pressure psi
GPM flow through inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☒ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
39 ft. after 5 hrs. pumping 14 gpm
ft. after hrs. pumping gpm
ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Top Soil	0	1
Yellow Sandy Till	1	8
Gray Clay	8	35
Coal	35	36
Fine Gray Sand	36	40
Sandy Gray Clay	40	50
Coal	50	59
Gray Clay	59	65

(Use separate sheet if necessary)

10. DATE COMPLETED 11-28-23

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS:

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

EEWS Inc. 153
Driller's or Firm's Name Certificate No.
New Salem ND
Address
Signed by 12-13-23
Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY