



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

JUN 06 2024

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

ND DEPT. OF WATER RESOURCES

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <u>East Fairview School</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>301 2nd St Fairview Mt 59221</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>11</u>			
		County <u>Mckenzie</u>		GPS		If Flowing, Closed-In Pressure In PSI	
Township <u>151</u>		Range <u>104</u>		Section <u>31</u>		GPM Flow Through Inch Pipe	
PROPOSED USE <u>15110431DAC</u>				Controlled By ☐ Valve ☐ Reducers ☐ Other			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial				WELL TEST DATA			
☐ Stock ☒ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other <u>Air</u>			
METHOD DRILLED				Pumping Level Below Land Surface <u>16 ft</u>			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary				Feet After <u>16</u>		Hrs. Pumping <u>2</u>	
☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After		Hrs. Pumping	
WATER QUALITY Was a water sample collected for				Feet After		Hrs. Pumping	
Chemical Analysis? ☐ Yes ☒ No						GPM	
Bacteriological Analysis? ☐ Yes ☒ No							
If So, To What Laboratory Was It Sent?							
WELL CONSTRUCTION				WELL LOG			
Diameter Of Hole In Inches <u>8-1/4</u>		Depth In Feet <u>44</u>		Formation		Depth (ft.)	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other		☐ Threaded ☐ Welded ☐ If Other, Specify _____				From To	
Pipe Weight lb/ft <u>250</u>	Diameter inches <u>4 1/2</u>	From feet <u>1 1/2</u>	To feet <u>40</u>	<u>clay</u>		<u>8</u> <u>8</u>	
				<u>sand</u>		<u>10</u> <u>10</u>	
				<u>gravel</u>		<u>11</u> <u>11</u>	
				<u>sand & clay</u>		<u>15</u> <u>15</u>	
				<u>gravel</u>		<u>32</u> <u>32</u>	
				<u>big gravel</u>		<u>44</u> <u>44</u>	
Was A Well Screen Installed? ☐ Yes ☒ No							
Was Perforated Pipe Used? ☒ Yes ☐ No							
Screen Or Perforation Interval		From In Feet <u>30</u>	To In Feet <u>40</u>				
Was Casing Left Open End? ☐ Yes ☒ No							
Material <u>PVC</u>		Diameter In Inches <u>4 1/2</u>					
Slot Size <u>650</u>	Set From In Feet <u>30</u>	To In Feet <u>40</u>		Use Separate Sheet If Necessary			
Slot Size	Set From In Feet	To In Feet		DATE COMPLETED <u>5/23/24</u>			
Was Packer Or Seal Used? ☐ Yes ☒ No				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
If So, What Material		Depth In Feet		If So, How			
Type Of Well ☒ Straight Screen ☒ Gravel Packed <u>10/40 sand</u>				REMARKS			
Depth Grouted	From <u>30</u>	To <u>30</u>					
Grouting Material	Cement	Other					
If Other, Explain: <u>Bentonite</u>							
Well Head Completion: Pitless Unit				DRILLER'S CERTIFICATION			
12" Above Grade ☒		Other (Specify)		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
It Other, Specify				Driller's Or Firm's Name <u>Sherrill Drilling Inc</u>		Certificate Number <u>101</u>	
				Address <u>601 E. 4th St Sidney Mt 59270</u>			
				Signed By <u>J. Sherrill</u>		Date <u>5/23/24</u>	