



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

OCT 22 2024

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

NO DEPT. OF WATER RESOURCES

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name John P. Wochos				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address 16046 35Q St NW East Fairview, MT 59221				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 1'			
		County McKenzie		GPS see remarks		If Flowing, Closed-In Pressure In PSI	
		1/4	1/4	1/4	GPM Flow Through Inch Pipe		
		Township 151N	Range 104W	Section 5	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____		
PROPOSED USE 15110405ACC				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other Air			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After Hrs. Pumping GPM 39 2 16			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.) From To			
WELL CONSTRUCTION				Brown clay 0 18			
Diameter Of Hole In Inches 12" - 50'		Depth In Feet 8" - 102'		Gravel 18 38			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				Sand & gravel 38 42			
Pipe Weight	Diameter	From	To	Brown Clay 42 54			
250 lb/ft	8 inches	2' above	50 feet	Sand 54 68			
250 lb/ft	4 1/2 inches	-0-	102 feet	Shale 68 85			
250 lb/ft	4 1/2 inches	-0-	102 feet	Coal 85 102			
Was A Well Screen Installed? ☐ Yes ☒ No				Shale/Coal layers 102 220			
Was Perforated Pipe Used? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Screen Or Perforation Interval		From In Feet	To In Feet	DATE COMPLETED 10/4/2024			
Was Casing Left Open End? ☐ Yes ☒ No				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Material Plastic - factory cut		Diameter In Inches 4 1/2		If So, How			
Slot Size 020	Set From In Feet 85	To In Feet 102		REMARKS			
Slot Size	Set From In Feet	To In Feet		Geographic location - 104 02190656 47 92905398			
Was Packer Or Seal Used? ☐ Yes ☒ No				DRILLER'S CERTIFICATION			
If So, What Material		Depth In Feet		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				Driller's Or Firm's Name Sharp Drilling, Inc.			
Depth Grouted	From	To		Certificate Number 101			
0		80		Address 601 8th Ave SE, Sidney, MT 59270			
Grouting Material		Cement	Other X	Signed By 			
If Other, Explain: Bentonite				Date 10/6/24			
Well Head Completion: Pitless Unit X							
12" Above Grade		Other (Specify)					
If Other, Specify							

COPY FOR BOARD

COPY FOR DRILLER

COPY FOR CUSTOMER