



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

MAR 10 2025

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Dean Haan</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>9670 53rd Ave SE Ashley, ND 58413</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>20</i>			
		County <i>McIntosh</i> GPS		If Flowing, Closed-In Pressure In PSI		GPM Flow Through Inch Pipe	
1/4 <i>SE</i>		1/4 <i>SW</i>		1/4 <i>SW</i>		Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify	
Township <i>129N</i>		Range <i>69W</i>		Section <i>1</i>			
PROPOSED USE <i>12906901CCD</i>				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other <i>Air</i>			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify				Feet After <i>25</i> Hrs. Pumping <i>4</i> GPM <i>10</i>			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☐ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☐ No				Feet After Hrs. Pumping GPM			
If So, To What Laboratory Was It Sent?				WELL LOG			
WELL CONSTRUCTION				Formation Depth (ft.)			
Diameter Of Hole In Inches <i>8 3/4</i>		Depth In Feet <i>49</i>		From To			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify				Topsoil <i>0 1</i>			
Pipe Weight lb/ft <i>SPR-21</i>	Diameter inches <i>5</i>	From feet <i>0</i>	To feet <i>29</i>	Yellow Clay <i>1 22</i>			
lb/ft	inches	feet	feet	Blue Clay <i>22 29</i>			
lb/ft	inches	feet	feet	Gray Sand <i>29 49</i>			
lb/ft	inches	feet	feet	Soft Blue Clay <i>49 56</i>			
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval	From In Feet	To In Feet					
Was Casing Left Open End? ☐ Yes ☒ No							
Material <i>PVC</i>		Diameter In Inches <i>5</i>		Use Separate Sheet If Necessary			
Slot Size <i>0.030</i>	Set From In Feet <i>29</i>	To In Feet <i>49</i>		DATE COMPLETED <i>9-18-24</i>			
Slot Size	Set From In Feet	To In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Was Packer Or Seal Used? ☐ Yes ☒ No				If So, How			
If So, What Material		Depth In Feet		REMARKS			
Type Of Well ☐ Straight Screen ☒ Gravel Packed							
Depth Grouted	From <i>0</i>	To <i>27</i>					
Grouting Material	Cement	Other <i>Grout-well</i>					
If Other, Explain: <i>Tremie Line pressure grouted from bottom to top</i>				DRILLER'S CERTIFICATION			
Well Head Completion: Pitless Unit <i>yes</i>				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" Above Grade <i>yes</i>	Other (Specify)			Driller's Or Firm's Name <i>Wieber Drilling LLC</i>		Certificate Number <i>211</i>	
It Other, Specify				Address <i>214 Wiley Ave S Lidgerwood, ND 58053</i>			
				Signed By <i>Derek Wieber</i>		Date <i>12-30-24</i>	