



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED
APR 01 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Marcus Knoll</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>2618 co. rd 136 St Anthony N.D.</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>78'</i>			
		County <i>Morton</i>		GPS <i>46.59724, -100.96251</i>		If Flowing, Closed-In Pressure In PSI	
		1/4 <i>NW</i>	1/4 <i>SE</i>	1/4 <i>SW</i>	1/4 <i>NW</i>	GPM Flow Through Inch Pipe	
		Township <i>136N</i>		Range <i>82W</i>		Section <i>14</i>	
PROPOSED USE <i>13608214BCD</i>				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <i>150</i> Hrs. Pumping <i>.05</i> GPM <i>4 gpm</i>			
WATER QUALITY Was a water sample collected for				Feet After <i>200</i> Hrs. Pumping <i>2</i> GPM <i>11 gpm</i>			
Chemical Analysis? ☒ Yes ☐ No <i>by owner</i>				Feet After <i>240</i> Hrs. Pumping <i>18</i> GPM <i>15</i>			
Bacteriological Analysis? ☒ Yes ☐ No <i>by owner</i>				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <i>8"</i>		Depth In Feet <i>360</i>		Brown clay		<i>0 47</i>	
Casing:				gray clay		<i>47 115</i>	
☐ Steel ☒ Plastic ☐ Concrete ☐ Other	☐ Threaded ☒ Welded ☐ If Other, Specify _____			gray sandy clay		<i>115 141</i>	
Pipe Weight	Diameter	From	To	gray clay		<i>141 210</i>	
<i>200</i> lb/ft	<i>4.5</i> inches	<i>0</i> feet	<i>360</i> feet	sandy clay seepage		<i>210 220</i>	
				gray clay		<i>220 224</i>	
				gray sandy clay		<i>224 273</i>	
				seepage		<i>273 276</i>	
				gray clay		<i>276 316</i>	
				fine gray sand		<i>316 322</i>	
				gray clay		<i>322 335</i>	
				fine gray sand		<i>335 339</i>	
				gray clay		<i>339 345</i>	
				med gray sand		<i>345 363</i>	
				gray sandy clay		<i>363 368</i>	
				soft coal.		<i>368 370</i>	
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☒ Yes ☐ No				DATE COMPLETED <i>1-3-25</i>			
Screen Or Perforation Interval		From In Feet <i>330</i>	To In Feet <i>360</i>	WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Was Casing Left Open End? ☐ Yes ☒ No				If So, How			
Material <i>PVC</i>		Diameter In Inches <i>4.5</i>		REMARKS			
Slot Size <i>.020</i>	Set From In Feet <i>330</i>	To In Feet <i>360</i>		<i>New Yard well</i>			
Slot Size	Set From In Feet	To In Feet		DRILLER'S CERTIFICATION			
Was Packer Or Seal Used? ☒ Yes ☐ No				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
If So, What Material <i>chips + cement</i>		Depth In Feet <i>8-330</i>		Driller's Or Firm's Name <i>Schaff and Sons Repair</i>		Certificate Number <i>14</i>	
Type Of Well ☐ Straight Screen ☒ Gravel Packed				Address <i>P.O. 339 Mandan N.D.</i>		Signed By <i>Bill Schaff</i> Date <i>1-30-25</i>	
Depth Grouted	From <i>8</i>	To <i>330</i>					
Grouting Material	<i>Cement</i>	Other <i>chips</i>					
If Other, Explain:							
Well Head Completion: Pitless Unit <i>4" Monitor</i>							
12" Above Grade <i>14"</i>		Other (Specify)					
It Other, Specify							