



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (11/2013)

RECEIVED

JUL 11 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was pump installed? ☐ Yes ☒ No			
Name Minot AFB				Was well disinfected upon completion? ☐ Yes ☒ No			
Address 165 Missile Ave Minot AFB, ND 58705				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static water level (in feet) below surface			
		County McHenry		GPS See Remarks		If flowing, closed-in pressure in psi	
		1/4 NW		1/4 NW		GPM flow Through inch pipe	
		Township 151N		Range 79W		Controlled by ☐ Valve ☐ Reducers ☐ Other	
		Section 33		☐ If other, specify			
PROPOSED USE 15107933888				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping level below land surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If other, specify				Feet after Hrs. pumping gpm			
WATER QUALITY Was a water sample collected for				Feet after Hrs. pumping gpm			
Chemical Analysis? ☐ Yes ☒ No				Feet after Hrs. pumping gpm			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If so, to what laboratory was it sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter of hole in inches 6" / (7-7/8")		Depth in feet 190' / (20')		brown clay		0 9	
Casing:				loose sand, caving		9 12	
☐ Steel ☒ Plastic ☐ Concrete ☐ Other				brown clay		12 30	
☐ Threaded ☐ Welded ☐ If other, specify				gray clay with some sand		30 130	
Pipe Weight	Diameter	From	To	firm gray clay		130 190	
lb/ft	inches	feet	feet				
sch40 solid pvc	1	0	30				
lb/ft	inches	feet	feet				
sch40 allvent pvc	1	30	190				
lb/ft	inches	feet	feet				
sch40 pvc	6	0	20				
Was perforated pipe used? ☐ Yes ☒ No							
Perforated pipe set from in feet		To in feet					
Was casing left open end? ☐ Yes ☐ No							
Was a well screen installed? ☐ Yes ☒ No							
Material		Diameter in inches					
Slot Size	Set from in feet	To in feet		(Use separate sheet if necessary)			
Slot Size	Set from in feet	To in feet					
Was packer or seal used? ☐ Yes ☐ No				DATE COMPLETED 7-2-2025			
If so, what material		Depth in feet		WAS WELL PLUGGED OR ABANDONED?			
Type of well ☐ Straight screen ☐ Gravel packed				☐ Yes ☒ No			
Depth grouted		From	To	REMARKS			
0		24		15107933NWNWNW			
Grouting Material		Cement	Other	47.86163262444565, -100.7996889913221 Google Maps			
Bentonite chips				10th Ave N, 31st St N Olivia TWP			
If other, explain:				B-6 Launch Facility			
Bentonite chips (0-15); Loresco SC-3 cokebreeze (15-190)				Deep Well Anode Ground Bed for Cathodic Protection			
Well head completion: Pitless unit				DRILLER'S CERTIFICATION			
12" above grade		Other		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
If other, specify				Driller's or Firm's Name Iba Drilling Company, Inc.		Certificate Number 209	
				Address PO Box 1041 Glendive, MT 59330		Date 7-2-2025	
				Signed by Chris Iba			