



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

AUG - 7 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name <i>Seth Barkley</i>				Was Well Disinfected Upon Completion? ☐ Yes ☒ No			
Address <i>Baker Mt.</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>40'</i>			
		County <i>Golden Valley</i>		GPS <i>46°47'54"N 103°54'3"W</i>		If Flowing, Closed-In Pressure In PSI	
1/4		1/4		1/4		GPM Flow Through Inch Pipe	
Township <i>138</i>		Range <i>105</i>		Section <i>2</i>		Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify	
PROPOSED USE <i>13810502BCB</i>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other <i>Art</i>			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify				Feet After <i>120</i> Hrs. Pumping <i>3</i> GPM <i>15</i>			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <i>8.75</i>		Depth In Feet <i>287'</i>		<i>Sand-brown-dirty</i> <i>0</i> <i>5</i>			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify				<i>Clay-white</i> <i>5</i> <i>8</i>			
Pipe Weight	Diameter	From	To	<i>Sand-brown</i> <i>8</i> <i>143</i>			
<i>200</i> lb/ft	<i>5</i> inches	<i>+3</i> feet	<i>267</i> feet	<i>rock</i> <i>143</i> <i>146</i>			
				<i>clay-white-powder</i> <i>146</i> <i>51</i>			
				<i>rock</i> <i>51</i> <i>60</i>			
				<i>clay-grey</i> <i>60</i> <i>90</i>			
				<i>rock</i> <i>90</i> <i>157</i>			
				<i>sand-grey-very fine</i> <i>157</i> <i>187</i>			
				<i>clay-dark grey</i> <i>187</i> <i>202</i>			
				<i>rock</i> <i>202</i> <i>211</i>			
				<i>sand-grey-very fine</i> <i>211</i> <i>240</i>			
				<i>clay-grey</i> <i>240</i> <i>250</i>			
				<i>sand-blueish-fine</i> <i>250</i> <i>287</i>			
				<i>rock</i> <i>287</i>			
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☐ Yes ☒ No				DATE COMPLETED <i>7-25-25</i>			
Screen Or Perforation Interval		From In Feet To In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
<i>207</i>		<i>287</i>		If So, How			
Was Casing Left Open End? ☐ Yes ☒ No				REMARKS			
Material <i>PVC</i>		Diameter In Inches <i>5 1/2</i>					
Slot Size <i>.020</i>		Set From In Feet To In Feet					
<i>267</i>		<i>287</i>					
Slot Size		Set From In Feet To In Feet					
Was Packer Or Seal Used? ☐ Yes ☒ No							
If So, What Material		Depth In Feet					
Type Of Well ☐ Straight Screen ☒ <i>Sand</i> Gravel Packed							
Depth Grouted		From To					
		<i>0</i> <i>255</i>					
Grouting Material		Cement Other					
		<i>Bestonite Clay</i>					
If Other, Explain:							
Well Head Completion: Pitless Unit <i>No</i>				DRILLER'S CERTIFICATION			
12" Above Grade		Other (Specify)		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
				Driller's Or Firm's Name <i>Milo Burwick & Sons LLC</i> Certificate Number <i>91</i>			
It Other, Specify				Address <i>Dockinson ND</i>			
				Signed By <i>Mike Burwick</i> Date <i>7-30-25</i>			