STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED
OCT 31 2025
ND DEPT. OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER

Name: Seth Demontigny
Address: 704 Jay ST
Bottineau ND. 58318

2. WELL LOCATION

Sketch map location must agree with written location.

48 51 22.807N
-102 13 27.031W

NORTH
1 MILE

1620 7414 CBB

#3

Sec. (1 mile) _____

County: Bottineau

NW 1/4 NW 1/4 SW 1/4 Sec. 14 Twp. 162 N. Rg. 74 W.

3. PROPOSED USE

☐ Domestic ☐ Stock ☐ Geothermal ☐ Irrigation ☐ Municipal ☐ Monitoring ☐ Industrial ☑ Test Hole

4. METHOD DRILLED

☐ Cable ☑ Forward Rotary ☐ Reverse Rotary ☐ Jetted ☐ Bored ☐ Auger

If other, specify _____

5. WATER QUALITY

Was a water sample collected for:
Chemical Analysis? ☐ Yes ☐ No
Bacteriological Analysis? ☐ Yes ☐ No
If so, to what laboratory was it sent? _____

6. WELL CONSTRUCTION

Diameter of hole: 5 5/8 inches. Depth: 160 feet.

Casing: ☐ Steel ☐ Plastic ☐ Concrete ☐ Threaded ☐ Welded ☐ Other

If other, specify _____

Pipe Weight:	Diameter:	From:	To:
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet
____ lb/ft	____ inches	____ feet	____ feet

Was perforated pipe used? ☐ Yes ☐ No
Perforated pipe set from _____ ft. to _____ feet
Was casing left open end? ☐ Yes ☐ No
Was a well screen installed? ☐ Yes ☐ No
Material _____ Diameter _____ inches
Slot Size _____ set from _____ feet to _____ feet
Slot Size _____ set from _____ feet to _____ feet
Was packer or seal used? ☐ Yes ☐ No
If so, what material _____ Depth _____ ft.
Type of well: Straight screen ☐ Gravel packed ☐
Depth grouted: From _____ To _____
Grouting Material: Cement _____ Other _____
If other, explain: _____
Well head completion: Pitless unit _____
12" above grade _____ Other _____
If other, specify _____
Was pump installed? ☐ Yes ☐ No
Was well disinfected upon completion? ☐ Yes ☐ No

7. WATER LEVEL

Static water level _____ feet below surface
If flowing: closed-in pressure _____ psi
GPM flow _____ through ____ inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify _____

8. WELL TEST DATA

☐ Pump ☐ Bailer ☐ Other
Pumping level below land surface:
_____ ft. after _____ hrs. pumping _____ gpm
_____ ft. after _____ hrs. pumping _____ gpm
_____ ft. after _____ hrs. pumping _____ gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Black overlay	0	1
yellow till	1	26
blue till	26	130
yellow silty clay + blue silty clay	130	155
grey shale	155	160

(Use separate sheet if necessary)

10. DATE COMPLETED 8-9-25

11. WAS WELL PLUGGED OR ABANDONED? ☑ Yes ☐ No
If so, how: Cuttings from hole + hole plug.

12. REMARKS: No formation encountered to work with.

13. DRILLER'S CERTIFICATION

This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Eldorado Drilling INC — Driller's or Firm's Name — 173 — Certificate No.
Box 733 Bottineau ND. 58318 — Address
Lane Ranson — Signed by — 8-9-25 — Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY