



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

DEC 12 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Terry Rocksted</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>3121 Valley Dr. Bismarck ND</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>286.4 top of pitless</i>			
		County <i>Billing</i>		GPS <i>Housewell</i>		If Flowing, Closed-In Pressure In PSI	
		1/4 <i>SE</i>	1/4 <i>SE</i>	1/4	<i>Drawdown 298.6</i>		
		Township <i>139</i>		Range <i>102</i>	Section <i>27</i>	GPM Flow Through Inch Pipe	
PROPOSED USE <i>13910227DD</i>				Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				WELL TEST DATA			
METHOD DRILLED				☒ Pump ☐ Bailer ☐ Other			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Pumping Level Below Land Surface			
WATER QUALITY Was a water sample collected for				Feet After <i>320</i> Hrs. Pumping <i>2</i> GPM <i>11</i>			
Chemical Analysis? ☒ Yes ☐ No <i>MVTL</i>				Feet After _____ Hrs. Pumping _____ GPM _____			
Bacteriological Analysis? ☐ Yes ☒ No				Feet After _____ Hrs. Pumping _____ GPM _____			
If So, To What Laboratory Was It Sent?				WELL LOG			
WELL CONSTRUCTION				Formation Depth (ft.)			
Diameter Of Hole In Inches <i>9 7/8</i>		Depth In Feet <i>360</i>		From		To	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				<i>Sand Lt. Brown</i> <i>0</i> <i>57</i>			
Pipe Weight	Diameter	From	To	<i>clay gray</i> <i>57</i> <i>149</i>			
lb/ft <i>SDR21</i>	inches <i>5</i>	feet <i>+1</i>	feet <i>311</i>	<i>Coal</i> <i>149</i> <i>162</i>			
lb/ft <i>SDR21</i>	inches <i>5</i>	feet <i>351</i>	feet <i>360</i>	<i>Sand Gray fine</i> <i>162</i> <i>196</i>			
lb/ft	inches	feet	feet	<i>clay gray</i> <i>196</i> <i>205</i>			
Was A Well Screen Installed? ☒ Yes ☐ No				<i>Coal</i> <i>205</i> <i>210</i>			
Was Perforated Pipe Used? ☐ Yes ☒ No				<i>clay gray</i> <i>210</i> <i>232</i>			
Screen Or Perforation Interval	From In Feet	To In Feet		<i>Sand Gray fine</i> <i>232</i> <i>262</i>			
Was Casing Left Open End? ☒ Yes ☐ No				<i>clay gray</i> <i>262</i> <i>307</i>			
Material <i>PVC SDR17</i>	Diameter In Inches <i>5</i>			<i>Sand Gray medium</i> <i>307</i> <i>351</i>			
Slot Size <i>16</i>	Set From In Feet <i>311</i>	To In Feet <i>351</i>		<i>clay gray</i> <i>351</i> <i>360</i>			
Slot Size	Set From In Feet	To In Feet		Use Separate Sheet If Necessary			
Was Packer Or Seal Used? ☒ Yes ☐ No				DATE COMPLETED <i>7-3-25</i>			
If So, What Material <i>Bentonite Chips</i>	Depth In Feet <i>280</i>			WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				If So, How			
Depth Grouted	From	To		REMARKS			
<i>6</i>	<i>6</i>	<i>30</i>					
Grouting Material	Cement	Other <i>Bentonite Chips</i>					
If Other, Explain:							
Well Head Completion: Pitless Unit <i>Yes</i>				DRILLER'S CERTIFICATION			
12" Above Grade <i>Yes</i> Other (Specify)				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
It Other, Specify				Driller's Or Firm's Name <i>Gregory and Sons Emergency</i> Certificate Number <i>154</i>			
				Address <i>3484 114th Ave SW Dickinson ND</i>			
				Signed By <i>Gregory</i> Date <i>7-30-25</i>			