



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

DEC 12 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name <i>John Hild</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>P.O. Box 384 Medora ND</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>267</i>			
		County <i>Billings</i>		GPS		If Flowing, Closed-In Pressure In PSI	
		1/4 <i>SE 1/4</i>	1/4 <i>SE 1/4</i>	1/4	GPM Flow Through Inch Pipe		
		Township <i>139</i>		Range <i>102</i>	Section <i>27</i>	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____	
PROPOSED USE <i>3910227DD</i>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <i>310</i> Hrs. Pumping <i>7</i> GPM <i>10</i>			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <i>9 3/8</i>		Depth In Feet <i>347</i>		Sand 2 ft. Brown		<i>0 24</i>	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				Rock <i>24 25</i>			
Pipe Weight	Diameter	From	To	Sand 1 ft. Brown <i>25 38</i>			
lb/ft	inches	feet	feet	Coal <i>38 39</i>			
<i>SDR 21</i>	<i>5</i>	<i>+1</i>	<i>280</i>	Clay Gray <i>39 60</i>			
lb/ft	inches	feet	feet	Coal <i>60 64</i>			
<i>SDR 21</i>	<i>5</i>	<i>340</i>	<i>347</i>	Clay Gray <i>64 72</i>			
lb/ft	inches	feet	feet	Coal <i>72 74</i>			
Was A Well Screen Installed? ☒ Yes ☐ No				Clay Gray <i>74 120</i>			
Was Perforated Pipe Used? ☐ Yes ☒ No				Sand Gray fine <i>120 130</i>			
Screen Or Perforation Interval	From In Feet	To In Feet		Clay Gray <i>130 135</i>			
Was Casing Left Open End? ☐ Yes ☒ No				Coal <i>135 152</i>			
Material <i>PVC SDR 17</i>	Diameter In Inches <i>5</i>			Clay Gray <i>152 180</i>			
Slot Size <i>16</i>	Set From In Feet <i>280</i>	To In Feet <i>340</i>		Coal <i>180 185</i>			
Slot Size	Set From In Feet	To In Feet		Clay Gray <i>185 279</i>			
Was Packer Or Seal Used? ☒ Yes ☐ No				Rock <i>279 280</i>			
If So, What Material <i>Bentonite chips</i>	Depth In Feet <i>256</i>			Sand Gray fine to medium <i>280 345</i>			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				Coal <i>345 347</i>			
Depth Grouted	From	To		Use Separate Sheet If Necessary			
	<i>0</i>	<i>30</i>		DATE COMPLETED <i>10-28-25</i>			
Grouting Material	Cement	Other <i>Bentonite chips</i>		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
If Other, Explain:				If So, How			
Well Head Completion: Pitless Unit <i>NU</i>				REMARKS			
12" Above Grade Other (Specify)				DRILLER'S CERTIFICATION			
It Other, Specify				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
				Driller's Or Firm's Name <i>Energy Water & Energy</i>		Certificate Number <i>154</i>	
				Address <i>3484 114th Ave SW Dickinson ND.</i>			
				Signed By <i>Larry A. Meyer</i>		Date <i>10-30-25</i>	