



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

DEC 11 2025

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <u>Mary Jane Miller Estate</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>3602 - 3rd St SW Underwood, ND 58576</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>111</u>			
		County <u>McLean</u>		GRS <u>Remarks</u>		If Flowing, Closed-In Pressure In PSI	
		1/4	1/4	1/4			
		Township	Range	Section			
PROPOSED USE <u>14508424ACB</u>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <u>155</u> Hrs. Pumping <u>4</u> GPM <u>8</u>			
WATER QUALITY Was a water sample collected for				Feet After _____ Hrs. Pumping _____ GPM _____			
Chemical Analysis? ☐ Yes ☒ No				Feet After _____ Hrs. Pumping _____ GPM _____			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <u>8 3/4 - 179 5-320</u>		Depth In Feet <u>well @ 175</u>		Brown clay		0 16	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				Grey clay		16 24	
Pipe Weight	Diameter	From	To	Coal		24 26	
lb/ft	inches	feet	feet	Grey clay		26 30	
<u>200</u>	<u>5</u>	<u>135</u>	<u>+3</u>	Coal		30 52	
lb/ft	inches	feet	feet	Grey clay		52 76	
lb/ft	inches	feet	feet	Coal		76 77	
				Grey clay		77 112	
				Coal Part @ 114		112 125	
				Grey clay		125 145	
				Pine sand		145 165	
				Silty clay		165 171	
				Coal		171 175	
				Grey clay		175 230	
				Coal		230 234	
				Grey clay		234 249	
				Coal		249 250	
				Grey clay		250 320	
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☐ Yes ☒ No				DATE COMPLETED <u>9-19-25</u>			
Screen Or Perforation Interval		From In Feet	To In Feet	WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
		<u>175</u>	<u>135</u>	If So, How			
Was Casing Left Open End? ☐ Yes ☒ No				REMARKS			
Material <u>PVC</u>		Diameter In Inches <u>5</u>		Elev 1827			
Slot Size <u>25</u>	Set From In Feet <u>175</u>	To In Feet <u>135</u>		47°22'04.03" N			
Slot Size	Set From In Feet	To In Feet		101°19'15.65" W			
Was Packer Or Seal Used? ☐ Yes ☒ No				DRILLER'S CERTIFICATION			
If So, What Material		Depth In Feet		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
				Driller's Or Firm's Name <u>Mohr Drilling</u> Certificate Number <u>106</u>			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				Address <u>Bear Lake ND 58523</u>			
Depth Grouted	From	To		Signed By <u>[Signature]</u> Date <u>9-19-25</u>			
	<u>130</u>	<u>0</u>					
Grouting Material	Cement	Other <u>Ben Seal</u>					
If Other, Explain:							
Well Head Completion: Pitless Unit							
12" Above Grade <u>X</u>	Other (Specify)						
It Other, Specify							