



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

Received by email
December 3, 2025

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER		Was Pump Installed? ☐ Yes ☒ No	
Name Odermann, Jon		Was Well Disinfected Upon Completion? ☒ Yes ☐ No	
Address 2399 East River Road, Medora, ND 58645		WATER LEVEL	
WELL LOCATION Sketch map location must agree with written location.		Static Water Level (In Feet) Below Surface	
	County Billings	GPS	
	1/4 SE	1/4 SE	1/4 SW
	Township 142	Range 101	Section 31
	If Flowing, Closed-In Pressure In PSI		
PROPOSED USE 14210131CDD		GPM Flow Through Inch Pipe 1.45 flow through 1" pipe	
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole		Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____	
METHOD DRILLED		WELL TEST DATA	
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____		☐ Pump ☐ Bailer ☒ Other air compressor	
WATER QUALITY Was a water sample collected for		Pumping Level Below Land Surface	
Chemical Analysis? ☒ Yes ☐ No		Feet After Hrs. Pumping GPM	
Bacteriological Analysis? ☒ Yes ☐ No		180 2 35	
If So, To What Laboratory Was It Sent? by owner		100 2 18	
WELL CONSTRUCTION		Feet After Hrs. Pumping GPM	
Diameter Of Hole In Inches 9		Depth In Feet 500	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____			
Pipe Weight 200 lb/ft	Diameter 5 inches	From 0 feet	To 205 feet
Pipe Weight 290 lb/ft	Diameter 5 inches	From 205 feet	To 365 feet
Pipe Weight lb/ft	Diameter inches	From feet	To feet
Was A Well Screen Installed? ☒ Yes ☐ No		WELL LOG	
Was Perforated Pipe Used? ☒ Yes ☐ No		Formation Depth (ft.) From To	
Screen Or Perforation Interval From In Feet To In Feet 365 465		topsoil 0 1	
Was Casing Left Open End? ☐ Yes ☒ No		brown sand 1 10	
Material pvc slotted		brown sand clay 10 25	
Slot Size .025	Set From In Feet 365	gray/br sand w/scoria chunks & coal layer 25 38	
Slot Size	Set From In Feet	gray clay sandy layer 38 80	
To In Feet 465		coal layer 80 85	
Was Packer Or Seal Used? ☐ Yes ☒ No		sandy gray clay 85 120	
If So, What Material		gray shale 120 180	
Depth In Feet		sandy gray shale 180 220	
Type Of Well ☐ Straight Screen ☒ Gravel Packed			gray shale 220 360
Depth Grouted From 0-60 & 100-120 To & 190-200			sandy gray shale 360 400
Grouting Material Cement Other			very fine gray sandy clay, layers of fine
bentonite chips			gray sand, somewhat silty 400 465
If Other, Explain:			gray shale 465 502
Well Head Completion: Pileless Unit			
12" Above Grade XX	Other (Specify)		
It Other, Specify			
DATE COMPLETED November 20, 2025		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No	
If So, How		If So, How	
REMARKS		DRILLER'S CERTIFICATION	
		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.	
		Driller's Or Firm's Name Certificate Number Dennis Water Well Drilling, Inc. 61	
		Address 10240 Highway 10, Gladstone, ND 58630-9530	
		Signed By Date James E. Dennis December 3, 2025	