



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (11/2013)

RECEIVED

JAN - 7 2026

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850

ND DEPT. OF WATER RESOURCES

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was pump installed? ☐ Yes ☒ No			
Name Marathon Petroleum				Was well disinfected upon completion? ☐ Yes ☒ No			
Address 19100 Ridgewood Parkway, San Antonio, TX 78259				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static water level (in feet) below surface			
		County McKenzie		GPS see remarks		If flowing, closed-in pressure in psi	
		1/4 SW	1/4 SE	1/4 SE	GPM flow Through inch pipe		
		Township 152N	Range 102W	Section 35	Controlled by ☐ Valve ☐ Reducers ☐ Other ☐ If other, specify		
					WELL TEST DATA		
PROPOSED USE 15210235CDD				☐ Pump ☐ Bailer ☐ Other			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				Pumping level below land surface			
METHOD DRILLED				Feet after Hrs. pumping gpm			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If other, specify				Feet after Hrs. pumping gpm			
WATER QUALITY Was a water sample collected for				Feet after Hrs. pumping gpm			
Chemical Analysis? ☐ Yes ☒ No				WELL LOG			
Bacteriological Analysis? ☐ Yes ☒ No				Formation Depth (ft.)			
If so, to what laboratory was it sent?				From To			
WELL CONSTRUCTION				brown clay 0 14			
Diameter of hole in inches 7-7/8"		Depth in feet 300'		coal 14 17			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If other, specify				brown clay 17 28			
Pipe Weight	Diameter	From	To	coal 28 34			
lb/ft	inches	feet	feet	firm gray clay 34 38			
sch 40 pvc solid	1	0	100	coal 38 40			
lb/ft	inches	feet	feet	firm gray clay 40 57			
sch 40 pvc all vent	1	100	300	sand with some firm gray clay 57 164			
lb/ft	inches	feet	feet	sandstone 164 166			
Was perforated pipe used? ☐ Yes ☐ No				sand with some firm gray clay 166 230			
Perforated pipe set from in feet		To in feet		firm gray clay 230 300			
Was casing left open end? ☐ Yes ☒ No							
Was a well screen installed? ☐ Yes ☒ No							
Material		Diameter in inches					
Slot Size		Set from in feet To in feet		(Use separate sheet if necessary)			
Slot Size		Set from in feet To in feet					
Was packer or seal used? ☐ Yes ☐ No				DATE COMPLETED 11-21-2025			
If so, what material		Depth in feet		WAS WELL PLUGGED OR ABANDONED?			
Type of well ☐ Straight screen ☐ Gravel packed				☐ Yes ☒ No			
Depth grouted feet		From To		If so, how			
0		115		REMARKS			
Grouting Material Bentonite grout		Cement Other		15210235SWSESE 47.93539173610085, -103.70108419092284 Google Maps 36th St NW, 146th Ave NW Tri TWP MPLX, "Alexander Station" Deep Well Anode Ground Bed for Cathodic Protection			
If other, explain: Wyoben Grout Well DF; Loresco SC-3 cokebreeze (115' - 300')				DRILLER'S CERTIFICATION			
Well head completion: Pitless unit				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" above grade		Other		Driller's or Firm's Name Iba Drilling Co., Inc.		Certificate Number 209	
If other, specify				Address PO Box 1041 Glendive, MT 59330		Date 11-21-2025	
				Signed by Chris Iba			