



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (11/2013)

RECEIVED

JAN - 7 2026

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

ND DEPT. OF WATER RESOURCES

WELL OWNER				Was pump installed? ☐ Yes ☒ No			
Name Marathon Petroleum				Was well disinfected upon completion? ☐ Yes ☒ No			
Address 19100 Ridgewood Parkway, San Antonio, TX 78259				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static water level (in feet) below surface			
		County Mercer		GPS see remarks		If flowing, closed-in pressure in psi	
		1/4 SE	1/4 SE	1/4 NW	GPM flow Through inch pipe		
		Township 143N	Range 89W	Section 01	Controlled by ☐ Valve ☐ Reducers ☐ Other ☐ If other, specify		
		PROPOSED USE 14308901DDDB				WELL TEST DATA	
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping level below land surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If other, specify				Feet after Hrs. pumping gpm			
WATER QUALITY Was a water sample collected for				Feet after Hrs. pumping gpm			
Chemical Analysis? ☐ Yes ☒ No				Feet after Hrs. pumping gpm			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If so, to what laboratory was it sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter of hole in inches 7-7/8"		Depth in feet 300'		brown clay		0	19
Casing:				coal		19	21
☐ Steel ☒ Plastic ☐ Concrete ☐ Other	☐ Threaded ☐ Welded ☐ If other, specify			firm gray clay		21	38
Pipe Weight lb/ft	Diameter inches	From feet	To feet	sandstone		38	39
sch 40 pvc solid 1	1	0	80	firm gray clay		39	145
sch 40 pvc allvent 1	1	80	300	firm gray clay with coal		145	170
				firm gray clay		170	190
				sandstone		190	192
				firm gray clay		192	270
				sand		270	300
Was perforated pipe used? ☐ Yes ☐ No							
Perforated pipe set from in feet		To in feet					
Was casing left open end? ☐ Yes ☒ No							
Was a well screen installed? ☐ Yes ☒ No							
Material		Diameter in inches					
Slot Size		Set from in feet To in feet		(Use separate sheet if necessary)			
Slot Size		Set from in feet To in feet					
Was packer or seal used? ☐ Yes ☐ No				DATE COMPLETED 11-23-2025			
If so, what material Depth in feet				WAS WELL PLUGGED OR ABANDONED?			
Type of well ☐ Straight screen ☐ Gravel packed				☐ Yes ☒ No			
Depth grouted feet		From To		If so, how			
0		88		REMARKS			
Grouting Material Bentonite grout		Cement Other		14308901SESENW 47.22976856004714, -101.89500086473927 Google Maps 13th St SW, 66th Ave SW Mercer UT MPLX, "Dunn Center to Mandan" Deep Well Anode Ground Bed for Cathodic Protection			
If other, explain: Wyoben Grout Well DF; Loresco SC-3 cokebreeze (88' - 300')				DRILLER'S CERTIFICATION			
Well head completion: Pitless unit				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" above grade		Other		Driller's or Firm's Name Iba Drilling Co., Inc.		Certificate Number 209	
If other, specify				Address PO Box 1041 Glendive, MT 59330		Date 11-23-2025	
				Signed by Chris Iba			