



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

JAN 09 2026

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Wolff Farms</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>1603 3rd St. NW, Hettinger ND 58639</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>2</i>			
		County <i>Adams</i>		GPS		If Flowing, Closed-In Pressure In PSI	
		1/4 <i>NW</i>	1/4	1/4	GPM Flow Through Inch Pipe		
		Township <i>132</i>	Range <i>96W</i>	Section <i>34</i>	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____		
PROPOSED USE <i>13209634B</i>				WELL TEST DATA			
☒ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☐ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <i>100</i> Hrs. Pumping <i>1 1/2</i> GPM <i>10</i>			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
Bacteriological Analysis? ☐ Yes ☒ No				Feet After Hrs. Pumping GPM			
If So, To What Laboratory Was It Sent?				WELL LOG			
WELL CONSTRUCTION				Formation Depth (ft.)			
Diameter Of Hole In Inches <i>7 1/2</i>		Depth In Feet <i>130</i>		From		To	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				clay		<i>0</i> <i>12</i>	
Pipe Weight		Diameter	From	To	sand	<i>12</i> <i>14</i>	
lb/ft	inches	feet	feet		rock	<i>14</i> <i>15</i>	
<i>200</i>	<i>5</i>	<i>0</i>	<i>130</i>		coal	<i>15</i> <i>19</i>	
lb/ft	inches	feet	feet		clay	<i>19</i> <i>74</i>	
lb/ft	inches	feet	feet		sandy clay	<i>74</i> <i>77</i>	
					clay	<i>77</i> <i>81</i>	
					coal	<i>81</i> <i>82</i>	
					clay	<i>82</i> <i>85</i>	
					sand	<i>85</i> <i>93</i>	
					clay	<i>93</i> <i>95</i>	
					coal	<i>95</i> <i>96</i>	
					sand	<i>96</i> <i>97</i>	
					rock	<i>97</i> <i>100</i>	
					sand	<i>100</i> <i>117</i>	
					rock	<i>117</i> <i>120</i>	
					sand	<i>120</i> <i>127</i>	
					rock	<i>127</i> <i>130</i>	
Was A Well Screen Installed? ☒ Yes ☐ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☐ Yes ☐ No				DATE COMPLETED <i>11-13-2024</i>			
Screen Or Perforation Interval		From In Feet <i>105</i>	To In Feet <i>130</i>	WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Was Casing Left Open End? ☒ Yes ☐ No				If So, How			
Material <i>PVC</i>		Diameter In Inches <i>5</i>		REMARKS			
Slot Size <i>16</i>	Set From In Feet <i>105</i>	To In Feet <i>130</i>					
Slot Size	Set From In Feet	To In Feet					
Was Packer Or Seal Used? ☐ Yes ☒ No							
If So, What Material		Depth In Feet					
Type Of Well ☐ Straight Screen ☒ Gravel Packed				DRILLER'S CERTIFICATION			
Depth Grouted		From <i>0</i>	To <i>98</i>	This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Grouting Material <i>ben-tonite</i>		Cement	Other	Driller's Or Firm's Name <i>Knutson Well Drilling Inc</i>		Certificate Number <i>70</i>	
If Other, Explain:				Address <i>Hettinger, ND 58639</i>			
Well Head Completion: Pitless Unit				Signed By <i>Robert Knutson</i>			
12" Above Grade <i>Yes</i>		Other (Specify)		Date <i>12/7/2024</i>			
It Other, Specify							