



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

JAN 09 2026

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name Benson Bros Ranch				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address Morristown, SD 57645				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 75 ft			
		County Sour		GPS		If Flowing, Closed-In Pressure In PSI	
		1/4	1/4	1/4			
		Township 129		Range 90 W	Section 36		
PROPOSED USE 12909036C				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify				Feet After 120			
WATER QUALITY Was a water sample collected for				Hrs. Pumping 1 1/2			
Chemical Analysis? ☒ Yes ☐ No				GPM 20			
Bacteriological Analysis? ☒ Yes ☐ No				Feet After			
If So, To What Laboratory Was It Sent?				Hrs. Pumping			
WELL CONSTRUCTION				GPM			
Diameter Of Hole In Inches 7 1/2		Depth In Feet 175 ft		WELL LOG			
Casing:				Formation		Depth (ft.)	
☐ Steel ☒ Plastic ☐ Concrete ☐ Other						From	To
☐ Threaded ☐ Welded ☐ If Other, Specify				gravel		0	2
Pipe Weight	Diameter	From	To	sandy and clay		2	33
lb/ft	inches	feet	feet	sandy clay		33	65
200	5	0	175	clay		65	77
lb/ft	inches	feet	feet	sand		77	87
lb/ft	inches	feet	feet	clay		87	100
				sand		100	133
				clay		133	138
				rock		138	139
				clay		139	152
				sand		152	175
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval		From In Feet	To In Feet				
		100	135				
		155	175				
Was Casing Left Open End? ☒ Yes ☐ No							
Material		Diameter In Inches					
PVC		5"					
Slot Size		Set From In Feet	To In Feet				
1/8"		100	135				
Slot Size		Set From In Feet	To In Feet				
1/8"		135	175				
Was Packer Or Seal Used? ☒ Yes ☐ No				DATE COMPLETED 8-1-2024			
If So, What Material		Depth In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
rubber		93'		If So, How			
Type Of Well ☒ Straight Screen ☐ Gravel Packed				REMARKS			
Depth Grouted		From	To				
		0	93'				
Grouting Material		Cement	Other				
			bentonite				
If Other, Explain:							
Well Head Completion: Pitless Unit				DRILLER'S CERTIFICATION			
12" Above Grade		Other (Specify)		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
well seal				Driller's Or Firm's Name		Certificate Number	
				Knutson Well Drilling Inc.		70	
It Other, Specify				Address			
				Hettinger ND 58639			
				Signed By		Date	
				Robert Knutson		9-22-2024	