STATE OF NORTH DAKOTA
BOARD OF WATER WELL CONTRACTORS
900 E. BOULEVARD AVE., DEPT. 770 • BISMARCK, NORTH DAKOTA 58505-0850

RECEIVED
JAN 28 2026
ND DEPT. OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

1. WELL OWNER
Name: Robert Marohl
Address: 15995 Co Rd 22
Hankinson, ND 58041

2. WELL LOCATION
Sketch map location must agree with written location.

GPS: 45° 59' 43" N, 97° 3' 27" W

EL: 129051100DDC

NORTH
1 MILE
Sec. (1 mile)

County: Richland
SW 1/4 SE 1/4 SE 1/4 Sec. 10 Twp. 129 N. Rg. 51 W.

3. PROPOSED USE
☐ Domestic ☐ Irrigation ☐ Industrial
☐ Stock ☐ Municipal ☐ Test Hole
☐ Geothermal ☐ Monitoring

4. METHOD DRILLED
☐ Cable ☐ Reverse Rotary ☐ Bored
☒ Forward Rotary ☐ Jetted ☐ Auger
If other, specify

5. WATER QUALITY
Was a water sample collected for:
Chemical Analysis? ☐ Yes ☒ No
Bacteriological Analysis? ☐ Yes ☒ No
If so, to what laboratory was it sent?

6. WELL CONSTRUCTION
Diameter of hole: 8 3/4 inches. Depth: 137 feet.
Casing: ☐ Steel ☒ Plastic ☐ Concrete
☐ Threaded ☐ Welded ☐ Other
If other, specify

Pipe Weight:	Diameter:	From:	To:
SDR-21 lb/ft	4 inches	0 feet	127 feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet

Was perforated pipe used? ☐ Yes ☒ No
Perforated pipe set from ft. to feet
Was casing left open end? ☐ Yes ☒ No
Was a well screen installed? ☒ Yes ☐ No
Material: PVC Diameter: 4 inches
Slot Size: 0.030 set from 127 feet to 137 feet
Slot Size set from feet to feet
Was packer or seal used? ☐ Yes ☒ No
If so, what material Depth ft.
Type of well: Straight screen ☐ Gravel packed ☒
Depth grouted: From 0 To 125
Grouting Material: Cement Other: Grout-Well
If other, explain: pressure grouted from bottom to top
Well head completion: Pitless unit: yes
12" above grade: yes Other
If other, specify
Was pump installed? ☒ Yes ☐ No
Was well disinfected upon completion? ☒ Yes ☐ No

7. WATER LEVEL
Static water level: 65 feet below surface
If flowing: closed-in pressure psi
GPM flow through inch pipe
Controlled by: ☐ Valve ☐ Reducers ☐ Other
If other, specify

8. WELL TEST DATA
☐ Pump ☐ Bailer ☒ Other: Air
Pumping level below land surface:
72 ft. after 4 hrs. pumping 10 gpm
ft. after hrs. pumping gpm
ft. after hrs. pumping gpm

9. WELL LOG

Formation	Depth (ft.) From	Depth (ft.) To
Topsoil	0	1
Fine Yellow Sand	1	15
Yellow Clay	15	53
Medium Yellow Sand	53	71
Yellow Gravel	71	74
Medium Yellow Sand	74	91
Medium Gray Sand	91	137
Blue Clay	137	140

(Use separate sheet if necessary)

10. DATE COMPLETED 6-10-25

11. WAS WELL PLUGGED OR ABANDONED?
☐ Yes ☒ No
If so, how

12. REMARKS: Garden well

13. DRILLER'S CERTIFICATION
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.

Wieber Drilling LLC — 211
Driller's or Firm's Name — Certificate No.
214 Wiley Ave S Lidgerwood, ND 58053
Address
Derek Wieber — 6-27-25
Signed by — Date

WHITE-BOARD'S COPY YELLOW-DRILLER'S COPY PINK-CUSTOMER'S COPY