



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

JAN 28 2026

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <u>Jesse Kalberer</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>Hazleton ND</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>225'</u>			
		County <u>Emmons</u>		GPS <u>46.43555</u> <u>-102.34388</u>		If Flowing, Closed-In Pressure In PSI	
		1/4 <u>NE of</u>	1/4 <u>NE of</u>	1/4 <u>NW</u>			
		Township <u>134N</u>	Range <u>77W</u>	Section <u>08</u>			
PROPOSED USE <u>134077080BA</u>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailer ☐ Other			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <u>260</u> Hrs. Pumping <u>6</u> GPM <u>12</u>			
WATER QUALITY Was a water sample collected for				Feet After _____ Hrs. Pumping _____ GPM _____			
Chemical Analysis? ☐ Yes ☒ No				Feet After _____ Hrs. Pumping _____ GPM _____			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <u>8 3/4</u>		Depth In Feet <u>340</u>		Black dirt		<u>0</u> <u>2</u>	
Casing:				Yellow clay		<u>2</u> <u>12</u>	
☐ Steel ☒ Plastic ☐ Concrete ☐ Other	☐ Threaded ☐ Welded ☐ If Other, Specify _____			medium gravel		<u>12</u> <u>22</u>	
Pipe Weight lb/ft <u>SDR 21</u>	Diameter inches <u>5</u>	From feet <u>+2</u>	To feet <u>220'</u>	SANDY Red CLAYS		<u>22</u> <u>50</u>	
				GRAY CLAY		<u>50</u> <u>158</u>	
				sandstone rock		<u>158</u> <u>160</u>	
				Fine sand + sandstone		<u>160</u> <u>205</u>	
				Layers - Dry			
				sandstone rock		<u>205</u> <u>206</u>	
				sand + sandstone layers		<u>206</u> <u>235</u>	
				sand + sandstone layers -		<u>235</u> <u>340</u>	
				sandstone soft			
				GRAY CLAY		<u>340</u> <u>400</u>	
Was A Well Screen Installed? ☐ Yes ☐ No							
Was Perforated Pipe Used? ☒ Yes ☐ No							
Screen Or Perforation Interval		From In Feet To In Feet					
Was Casing Left Open End? ☐ Yes ☒ No							
Material <u>PVC</u>		Diameter In Inches <u>5"</u>		Use Separate Sheet If Necessary			
Slot Size <u>16</u>		Set From In Feet <u>220</u> To In Feet <u>340</u>		DATE COMPLETED <u>1-4-26</u>			
Slot Size		Set From In Feet To In Feet		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☐ No			
Was Packer Or Seal Used? ☐ Yes ☒ No				If So, How			
If So, What Material		Depth In Feet		REMARKS			
Type Of Well ☐ Straight Screen ☒ Gravel Packed							
Depth Grouted		From <u>220 - 160</u> To <u>100 - 50</u>					
Grouting Material		Cement <u>Bentonite</u> Other					
If Other, Explain:							
Well Head Completion: Pitless Unit				DRILLER'S CERTIFICATION			
12" Above Grade ☒		Other (Specify)		This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
It Other, Specify				Driller's Or Firm's Name <u>Quicksilver well</u>		Certificate Number <u>131</u>	
				Address <u>Sterling ND</u>			
				Signed By <u>Y Ry</u>		Date <u>1-19-26</u>	