



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

FEB 09 2026

ND BOYD OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name: <u>Tommie Tank</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address: <u>13249 SW 136th PL Portland Oregon 97223</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>61</u>			
		County <u>McKenzie</u>		GPS <u>47.91654</u> <u>-102.95601</u>		If Flowing, Closed-In Pressure In PSI	
		1/4 <u>SW</u>	1/4 <u>NE</u>	1/4 <u>NW</u>			
		Township <u>151</u>		Range <u>96</u>		Section <u>10</u>	
PROPOSED USE <u>1510961DBAC</u>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other <u>Air</u>			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <u>96</u> Hrs. Pumping <u>2</u> GPM <u>10</u>			
WATER QUALITY Was a water sample collected for				Feet After _____ Hrs. Pumping _____ GPM _____			
Chemical Analysis? ☐ Yes ☒ No				Feet After _____ Hrs. Pumping _____ GPM _____			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent?				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <u>8 3/4"</u>		Depth In Feet <u>96</u>		<u>top soil</u> <u>0</u> <u>2</u>			
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other				<u>sand scoria</u> <u>2</u> <u>4</u>			
☐ Threaded ☐ Welded ☐ If Other, Specify _____				<u>brown sand</u> <u>4</u> <u>34</u>			
Pipe Weight	Diameter	From	To	<u>sandy clay brown</u> <u>34</u> <u>75</u>			
<u>SDR17</u>	<u>4.5</u>	<u>+2</u>	<u>86</u>	<u>gray sand/blue sand (medium)</u> <u>75</u> <u>94</u>			
lb/ft	inches	feet	feet	<u>coal</u> <u>94</u> <u>95</u>			
lb/ft	inches	feet	feet	<u>clay blue</u> <u>95</u> <u>96</u>			
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval	From In Feet	To In Feet					
Was Casing Left Open End? ☐ Yes ☒ No							
Material <u>PVC</u>	Diameter In Inches <u>4.5</u>			Use Separate Sheet If Necessary			
Slot Size <u>20</u>	Set From In Feet <u>86</u>	To In Feet <u>96</u>					
Slot Size	Set From In Feet	To In Feet					
Was Packer Or Seal Used? ☐ Yes ☒ No				DATE COMPLETED <u>11/4/2025</u>			
If So, What Material				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Depth In Feet				If So, How			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				REMARKS			
Depth Grouted	From <u>40</u>	To <u>surface</u>					
Grouting Material	Cement	Other ☒					
If Other, Explain: <u>hole plug</u>							
Well Head Completion: Pitless Unit				DRILLER'S CERTIFICATION			
12" Above Grade ☒				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Other (Specify)				Driller's Or Firm's Name <u>Thompson Drilling Inc</u> Certificate Number <u>205</u>			
It Other, Specify				Address <u>13544 28th St NW Arnegard ND 58835</u>			
				Signed By _____ Date <u>11/4/2025</u>			