



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2020)

RECEIVED

FEB 12 2026

ND DEPT. OF WATER RESOURCES

ND Board of Water Well Contractors • 900 E. Boulevard Ave. - Dept. 770 • Bismarck, ND, 58505-0850
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☒ Yes ☐ No			
Name <i>Kelly Moldenhauer</i>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <i>5280 58th St SW Carson ND</i>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <i>18'</i>			
		County <i>Grant</i>		GPS <i>46.52891,</i>		If Flowing, Closed-In Pressure In PSI	
		1/4	1/4	1/4			
		<i>-101.55054</i>					
Township		Range		Section		GPM Flow Through Inch Pipe	
Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify							
PROPOSED USE <i>13508712AAD</i>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☒ Pump ☐ Bailer ☐ Other <i>+ Jetted air</i>			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify				Feet After <i>30'</i> Hrs. Pumping <i>1/2</i> GPM <i>5</i>			
WATER QUALITY Was a water sample collected for				Feet After <i>20'</i> Hrs. Pumping <i>2</i> GPM <i>8</i>			
Chemical Analysis? ☐ Yes ☒ No				Feet After <i>90</i> Hrs. Pumping <i>4</i> GPM <i>11</i>			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent? <i>at owner discretion</i>				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <i>8"</i>		Depth In Feet <i>105ft</i>		<i>Brown sand</i>		<i>0 24</i>	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☒ Welded ☐ If Other, Specify				<i>Brown sandstone</i> <i>24 26</i>			
Pipe Weight lb/ft <i>200</i>		Diameter inches <i>4.5</i>		<i>Brown sand</i> <i>26 29</i>			
lb/ft		feet		<i>hard rock (gray)</i> <i>29 31</i>			
lb/ft		feet		<i>gray fine sand</i> <i>31 48</i>			
lb/ft		feet		<i>gray silty clay</i> <i>48 97</i>			
lb/ft		feet		<i>gray clay</i> <i>97 110</i>			
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☒ Yes ☐ No							
Screen Or Perforation Interval		From In Feet <i>20'</i> To In Feet <i>105'</i>					
Was Casing Left Open End? ☐ Yes ☒ No							
Material <i>PVC</i>		Diameter In Inches <i>4.5</i>					
Slot Size <i>.020</i>		Set From In Feet <i>20'</i> To In Feet <i>105'</i>		Use Separate Sheet If Necessary			
Slot Size		Set From In Feet To In Feet		DATE COMPLETED <i>8-28-25</i>			
Was Packer Or Seal Used? ☒ Yes ☐ No				WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
If So, What Material <i>chips</i>		Depth In Feet <i>0' - 20'</i>		If So, How			
Type Of Well ☐ Straight Screen ☒ Gravel Packed				REMARKS			
Depth Grouted		From <i>0</i> To <i>20'</i>		<i>Pasture Well - Pressurized Pipe Line</i>			
Grouting Material		Cement Other					
If Other, Explain: <i>chips</i>				DRILLER'S CERTIFICATION			
Well Head Completion: Pitless Unit <i>4" Monitor</i>				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" Above Grade <i>14"</i>		Other (Specify)		Driller's Or Firm's Name <i>Schaff and Sons Repair</i>		Certificate Number <i>14</i>	
It Other, Specify				Address <i>P.O. Box 339 Mandan</i>			
				Signed By <i>Bill Schaff</i>		Date <i>9-10-25</i>	