



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

DEC 22 2025

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name <u>Roark Franklund</u>				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address <u>Wilton, ND</u>				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface <u>110</u>			
		County <u>McLean</u>		GPS <u>47.164775</u> <u>-100.885796</u>		If Flowing, Closed-In Pressure In PSI	
		1/4 <u>SW</u>	1/4 <u>SW</u>	1/4 <u>NE</u>	GPM Flow Through Inch Pipe		
		Township <u>143N</u>		Range <u>81W</u>	Section <u>36</u>	Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____	
PROPOSED USE <u>14308136ACC</u>				WELL TEST DATA			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				☐ Pump ☐ Bailer ☒ Other <u>Air</u>			
METHOD DRILLED				Pumping Level Below Land Surface			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Feet After <u>360</u> Hrs. Pumping <u>1</u> GPM <u>9</u>			
WATER QUALITY Was a water sample collected for				Feet After <u>405</u> Hrs. Pumping <u>2</u> GPM <u>10</u>			
Chemical Analysis? ☐ Yes ☒ No				Feet After _____ Hrs. Pumping _____ GPM _____			
Bacteriological Analysis? ☐ Yes ☒ No				WELL LOG			
If So, To What Laboratory Was It Sent? <u>Left up To owner</u>				Formation Depth (ft.)			
WELL CONSTRUCTION				From To			
Diameter Of Hole In Inches <u>8</u>		Depth In Feet <u>588</u>		TOP SOIL <u>Brown sand w/some clay</u> 0 4			
Casing:		☒ Plastic ☐ Concrete ☐ Other		<u>Red sandstone</u> 4 11			
☐ Steel ☒ Threaded ☐ Welded ☐ If Other, Specify _____				<u>Brown sand</u> 11 25			
Pipe Weight	Diameter	From	To	<u>sandstone</u> 25 32			
<u>SDR 17</u>	<u>4 1/2</u>	<u>0</u>	<u>587</u>	<u>Brown sand</u> 32 37			
lb/ft	inches	feet	feet	<u>Grey clay</u> 37 45			
				<u>fine grey sandy clay</u> 45 80			
				<u>Brown clay</u> 80 102			
				<u>Grey clay some blue sand</u> 102 111			
				<u>Grey clay</u> 111 127			
				<u>Rock</u> 127 156			
				<u>Grey clay</u> 156 284			
				<u>Rock</u> 284 316			
				<u>Rock</u> 316 326			
				<u>Rock</u> 326 328			
				<u>Rock</u> 328 329			
				<u>Grey clay</u> 329 337			
				<u>Rock</u> 337 339			
				<u>Grey clay</u> 339 399			
				<u>shale seam</u> 399 399			
				<u>Grey clay</u> 399 469			
				<u>Sandy Blue clay</u> 469 474			
				<u>Rock</u> 474 475			
				<u>Sandy Blue clay</u> 475 480			
				<u>Grey clay w/seams of sand</u> 480 588			
Was A Well Screen Installed? ☐ Yes ☒ No				Use Separate Sheet If Necessary			
Was Perforated Pipe Used? ☒ Yes ☐ No				DATE COMPLETED <u>November 11, 2025</u>			
Screen Or Perforation Interval		From In Feet	To In Feet	WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
		<u>467</u>	<u>587</u>	If So, How			
Was Casing Left Open End? ☐ Yes ☒ No				REMARKS			
Material <u>PVC</u>		Diameter In Inches <u>4 1/2</u>					
Slot Size <u>.020</u>		Set From In Feet <u>467</u>	To In Feet <u>587</u>				
Slot Size		Set From In Feet	To In Feet				
Was Packer Or Seal Used? ☐ Yes ☒ No							
If So, What Material		Depth In Feet					
Type Of Well ☐ Straight Screen ☒ Gravel Packed							
Depth Grouted		From <u>15</u>	To <u>45</u>				
Grouting Material		Cement	Other ☒				
If Other, Explain: <u>sodium bentonite</u>				DRILLER'S CERTIFICATION			
Well Head Completion: Pitless Unit				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
12" Above Grade ☒		Other (Specify)		Driller's Or Firm's Name <u>Backman Drilling</u>		Certificate Number <u>#9</u>	
It Other, Specify				Address <u>30603 Hwy 83, Wilton, ND</u>		Signed By <u>Rex T. Paul</u> Date <u>12-4-2025</u>	