



WELL DRILLER'S REPORT
NORTH DAKOTA BOARD OF WATER WELL CONTRACTORS
STATE OF NORTH DAKOTA
SFN 60273 (8/2023)

RECEIVED

DEC 22 2025

NO STATE OF WATER RESOURCES

ND Board of Water Well Contractors • 1200 Memorial Highway • Bismarck, ND, 58504

State law requires that this report be filed with the State Board of Water Well Contractors within 30 days after completion or abandonment of the well.

WELL OWNER			
Name <u>Glenda Scholl</u>			
Address <u>Washburn, ND 47.301474</u> <u>P-101.253263</u>			
WELL LOCATION			
Sketch map location must agree with written location.			
		County <u>McLean</u>	GPS <u>47.301474</u> <u>P-101.253263</u>
1/4 <u>NE</u>	1/4 <u>NW</u>	1/4 <u>NW</u>	
Township <u>144N</u>		Range <u>83W</u>	Section <u>718</u>
PROPOSED USE			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole			
METHOD DRILLED			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____			
WATER QUALITY			
Was a water sample collected for			
Chemical Analysis? ☐ Yes ☒ No			
Bacteriological Analysis? ☐ Yes ☒ No			
If So, To What Laboratory Was It Sent? <u>Left up to owner</u>			
WELL CONSTRUCTION			
Diameter Of Hole In Inches <u>8</u>		Depth In Feet <u>535</u>	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____			
Pipe Weight	Diameter	From	To
<u>SDR17</u>	<u>4 1/2</u>	<u>0</u>	<u>530</u>
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet
lb/ft	inches	feet	feet
Was A Well Screen Installed? ☐ Yes ☒ No			
Was Perforated Pipe Used? ☒ Yes ☐ No			
Screen Or Perforation Interval		From In Feet	To In Feet
		<u>490</u>	<u>530</u>
Was Casing Left Open End? ☐ Yes ☒ No			
Material <u>PVC</u>		Diameter In Inches <u>4 1/2</u>	
Slot Size	Set From In Feet	To In Feet	
<u>.020</u>	<u>490</u>	<u>530</u>	
Slot Size	Set From In Feet	To In Feet	
Was Packer Or Seal Used? ☐ Yes ☒ No			
If So, What Material		Depth In Feet	
Type Of Well ☐ Straight Screen ☒ Gravel Packed			
Depth Grouted		From	To
		<u>20</u>	<u>50</u>
Grouting Material		Cement	Other ☒
If Other, Explain: <u>sodium bentonite</u>			
Well Head Completion: Pitless Unit <u>Monitor</u>			
12" Above Grade ☒		Other (Specify)	
It Other, Specify			
Was Pump Installed? ☒ Yes ☐ No			
Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
WATER LEVEL			
Static Water Level (In Feet) Below Surface <u>N/A</u>			
If Flowing, Closed-In Pressure In PSI			
GPM Flow		Through	Inch Pipe
Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____			
WELL TEST DATA			
☐ Pump ☐ Bailor ☒ Other <u>Air</u>			
Pumping Level Below Land Surface			
Feet After	Hrs. Pumping	GPM	
<u>300</u>	<u>1/4</u>	<u>4</u>	
Feet After	Hrs. Pumping	GPM	
<u>395</u>	<u>1/4</u>	<u>4 1/2</u>	
Feet After	Hrs. Pumping	GPM	
<u>440</u>	<u>2</u>	<u>5</u>	
WELL LOG			
Formation		Depth (ft.)	
		From	To
<u>Topsoil</u>		<u>0</u>	<u>1</u>
<u>Brown sandy clay</u>		<u>1</u>	<u>11</u>
<u>Brown clay</u>		<u>11</u>	<u>21</u>
<u>Brown sand</u>		<u>21</u>	<u>42</u>
<u>Brown clay</u>		<u>42</u>	<u>44</u>
<u>Grey clay</u>		<u>44</u>	<u>63</u>
<u>Grey clay w/ coal + streaks</u>		<u>63</u>	<u>74</u>
<u>Grey clay</u>		<u>74</u>	<u>86</u>
<u>Shale</u>		<u>86</u>	<u>87</u>
<u>Grey clay</u>		<u>87</u>	<u>146</u>
<u>Coal</u>		<u>146</u>	<u>147</u>
<u>Grey clay</u>		<u>147</u>	<u>158</u>
<u>Shale seam</u>		<u>158</u>	<u>158</u>
<u>Grey clay w/ coal seams</u>		<u>158</u>	<u>164</u>
<u>Grey clay</u>		<u>164</u>	<u>199</u>
<u>Brown clay w/ coal seams</u>		<u>199</u>	<u>210</u>
<u>Shale</u>		<u>210</u>	<u>213</u>
<u>Green clay</u>		<u>213</u>	<u>214</u>
<u>Grey clay</u>		<u>214</u>	<u>218</u>
<u>Shale seam</u>		<u>218</u>	<u>272</u>
<u>Grey clay</u>		<u>272</u>	<u>274</u>
<u>Shale seam</u>		<u>274</u>	<u>274</u>
<u>Grey clay</u>		<u>274</u>	<u>274</u>
<u>Shale</u>		<u>274</u>	<u>295</u>
<u>Grey clay w/ coal and Brown clay streaks</u>		<u>295</u>	<u>296</u>
<u>Shale</u>		<u>296</u>	<u>314</u>
<u>Grey clay</u>		<u>314</u>	<u>325</u>
<u>Sandy grey clay</u>		<u>325</u>	<u>326</u>
<u>Grey clay</u>		<u>326</u>	<u>331</u>
<u>Shale</u>		<u>331</u>	<u>345</u>
<u>Grey clay</u>		<u>345</u>	<u>384</u>
<u>Shale</u>		<u>384</u>	<u>385</u>
<u>Grey clay</u>		<u>385</u>	<u>405</u>
<u>Shale</u>		<u>405</u>	<u>405</u>
<u>Grey sandy clay</u>		<u>405</u>	<u>495</u>
<u>Shale seam</u>		<u>495</u>	<u>496</u>
<u>Blue sandy clay</u>		<u>496</u>	<u>508</u>
<u>Rock</u>		<u>508</u>	<u>510</u>
Use Separate Sheet If Necessary			
<u>Blue sandy clay</u>		<u>510 - 530</u>	
<u>Grey clay</u>		<u>530 - 535</u>	
DATE COMPLETED			
<u>December 15, 2025</u>			
WAS WELL PLUGGED OR ABANDONED?			
☐ Yes ☒ No			
If So, How			
REMARKS			
DRILLER'S CERTIFICATION			
This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Driller's Or Firm's Name		Certificate Number	
<u>Bachman Drilling</u>		<u>#9</u>	
Address			
<u>30603 Hwy 83, Wilton, ND</u>			
Signed By		Date	
<u>Rex T. Burt</u>		<u>12-17-2025</u>	