



WELL DRILLER'S REPORT
NORTH DAKOTA DEPARTMENT OF WATER RESOURCES
WATER APPROPRIATION
SFN 60273 (7/2025)

RECEIVED

MAR 25 2026

Department of Water Resources • 1200 Memorial Highway • Bismarck, ND, 58504
State law requires that this report be filed with the Department of Water Resources within 30 days after completion or abandonment of the well. ND DEPT. OF WATER RESOURCES

WELL OWNER				Was Pump Installed? ☐ Yes ☒ No			
Name Joe Jackman				Was Well Disinfected Upon Completion? ☒ Yes ☐ No			
Address 6418 133rd Ave NW				WATER LEVEL			
WELL LOCATION Sketch map location must agree with written location.				Static Water Level (In Feet) Below Surface 21			
		County Williams		GPS		If Flowing, Closed-In Pressure In PSI N/A	
		1/4 SW		1/4 SW		GPM Flow Through Inch Pipe	
		Township 156N		Range 100W		Section 9	
PROPOSED USE 15610009CC				Controlled By ☐ Valve ☐ Reducers ☐ Other ☐ If Other, Specify _____			
☐ Domestic ☐ Geothermal ☐ Municipal ☐ Industrial ☒ Stock ☐ Irrigation ☐ Monitoring ☐ Test Hole				WELL TEST DATA			
METHOD DRILLED				☒ Pump ☐ Bailer ☐ Other			
☐ Cable ☐ Jetted ☒ Forward Rotary ☐ Reverse Rotary ☐ Bored ☐ Auger ☐ If Other, Specify _____				Pumping Level Below Land Surface			
WATER QUALITY Was a water sample collected for				Feet After Hrs. Pumping GPM			
Chemical Analysis? ☐ Yes ☒ No				32 1 5			
Bacteriological Analysis? ☒ Yes ☐ No				Feet After Hrs. Pumping GPM			
If So, To What Laboratory Was It Sent? Astro-Chem, Williston, ND				Feet After Hrs. Pumping GPM			
WELL CONSTRUCTION				WELL LOG			
Diameter Of Hole In Inches 8.75"		Depth In Feet 100		Formation		Depth (ft.) From To	
Casing: ☐ Steel ☒ Plastic ☐ Concrete ☐ Other ☐ Threaded ☐ Welded ☐ If Other, Specify _____				Silt		0 8	
Pipe Weight	Diameter	From	To	Gravel		8 22	
lb/ft	inches	feet	feet	Gray Clay		22 65	
lb/ft	inches	feet	feet	Sand		65 80	
lb/ft	inches	feet	feet	Gravel		80 100	
Was A Well Screen Installed? ☒ Yes ☐ No							
Was Perforated Pipe Used? ☐ Yes ☒ No							
Screen Or Perforation Interval		From In Feet	To In Feet				
Was Casing Left Open End? ☐ Yes ☒ No							
Material Stainless Steel Screen		Diameter In Inches 5		Use Separate Sheet If Necessary			
Slot Size	Set From In Feet	To In Feet		DATE COMPLETED 3-15-2025			
20	90	100		WAS WELL PLUGGED OR ABANDONED? ☐ Yes ☒ No			
Slot Size	Set From In Feet	To In Feet		If So, How			
Was Packer Or Seal Used? ☐ Yes ☒ No				REMARKS			
If So, What Material Bentonite Chip		Depth In Feet					
Type Of Well ☐ Straight Screen ☒ Gravel Packed							
Depth Grouted Bentonite Chips	From	To					
Grouting Material	Cement	Other		DRILLER'S CERTIFICATION			
If Other, Explain:				This well was drilled under my jurisdiction and this report is true to the best of my knowledge.			
Well Head Completion: Pitless Unit Customer Completed Well				Driller's Or Firm's Name Agri Industries Inc.			
12" Above Grade yes		Other (Specify)		License Number 123		Address 3105 2nd St West, Williston, ND 58801	
If Other, Specify				Signed <i>[Signature]</i>		Date 24 March 2025	

COPY FOR DWR

COPY FOR DRILLER

COPY FOR CUSTOMER